

Cleanup Site Details

Cleanup Site ID: 7088

Cleanup Site ID: 7088 Facility/Site ID: 47245321 UST ID: 97284 [Site Page](#) [Site Documents](#) [View Map](#)
 Cleanup Site Name: Ward Rugh Inc [Glossary](#)
 Alternate Names: Ward Rugh Inc, Ward Rugh Trucking

LOCATION
 Address: 710 W UNIVERSITY WAY City: ELLENSBURG Zip Code: 98926 County: Kittitas
 Latitude: 46.99925 Longitude: -120.55671 WRIA: 39 Legislative District: 13 Congressional District: 8 TRS: 17N 18E 2

DETAIL
 Status: No Further Action NFA Received? Yes Is PSI site? No
 Statute: MTCA NFA Date: 1/31/2024 Current VCP? No Past VCP? Yes
 Site Rank: 2 - Moderate-High Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No
 Site Manager: Winslow, Frank Responsible Unit: Central Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Ward Rugh Trucking	Upland	No Further Action Required	CE	Winslow, Frank	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Prohibit Soil Disturbance	7/30/2019	201907300099	Kittitas	397833

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RA					
Petroleum-Gasoline	RA	RB				
Petroleum-Other	RA					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		12/6/1990
LUST - Report Received	Completed		2/1/1991
LUST - Report Received	Completed		3/14/1991
Site Discovery/Release Report Received	Completed		12/9/1993
LUST - Notification	Completed		12/9/1993
LUST - Report Received	Completed		2/2/1994
Early Notice Letter(s)	Completed		10/29/2007

Cleanup Site Details

Cleanup Site ID: 7088

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	1/1/2011	2/1/2011
Site Hazard Assessment/Federal Site Inspection	Completed	1/2/2012	1/20/2012
Hazardous Sites Listing/NPL	Completed		1/20/2012
VCP Opinion on Site Cleanup Plan	Completed	11/16/2017	11/29/2017
LUST - Report Received	Completed		11/20/2017
VCP Opinion on Site Cleanup	Completed	7/11/2018	7/12/2018
LUST - Report Received	Completed		7/13/2018
VCP Technical Assistance	Completed		11/1/2018
LUST - Report Received	Completed		11/6/2018
LUST - Report Received	Completed		12/31/2018
LUST - Report Received	Completed		3/25/2019
VCP Opinion on Site Cleanup	Completed	9/3/2019	9/27/2019
Petroleum Impacts to Groundwater Model Remedies	Completed		9/27/2019
Remove site from Hazardous Sites List	Completed		1/31/2024
Site Status Changed to NFA	Completed		1/31/2024
Periodic Review	Planned	10/1/2028	1/31/2029