

Cleanup Site Details

Cleanup Site ID: 7093

Cleanup Site ID: 7093 Facility/Site ID: 53481373 UST ID: 11034 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Kaiser Aluminum & Chemical Corporation [Glossary](#)

Alternate Names: Kaiser Aluminum, Kaiser Aluminum & Chemical Corporation, KAISER ALUMINUM & CHEMICAL INC, KAISER ALUMINUM & CHEMICAL INC UST 11034, KAISER ALUMINUM FABRICATED PRODUCTS, KAISER ALUMINUM FABRICATED PRODUCTS LLC, KAISER ALUMINUM TRENTWOOD, KAISER TRENTWOOD, TRENTWOOD PLANT

LOCATION

Address: 15000 E EUCLID AVE **City:** SPOKANE **Zip Code:** 99216 **County:** Spokane
Latitude: 47.68605 **Longitude:** -117.20560 **WRIA:** 57 **Legislative District:** 4 **Congressional District:** 5 **TRS:** 25N 44E 2

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Schmidt, Jeremy **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
KAISER-TRENTWOOD	Upland	Cleanup Started	EA	Eastern Region	Ecology-supervised or conducted
KAISER-TRENTWOOD	Upland	Cleanup Started	EA	Eastern Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	C	C				
Metals Priority Pollutants	C		S			
Petroleum Products-Unspecified		C	S			
Petroleum-Other	C					
Polychlorinated biPhenyls (PCB)	C	C	S			

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	10/19/1988	12/19/1988
Early Notice Letter(s)	Completed		3/21/1991
Initial Investigation / Federal Preliminary Assessment	Completed		3/21/1991
LUST - Notification	Completed		4/29/1991

Cleanup Site Details

Cleanup Site ID: 7093

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		5/13/1991
LUST - Report Received	Completed		6/3/1991
Initial Investigation / Federal Preliminary Assessment	Completed		6/27/1991
Early Notice Letter(s)	Completed		10/11/1991
Site Discovery/Release Report Received	Completed		2/14/1992
Initial Investigation / Federal Preliminary Assessment	Completed		3/4/1992
Site Discovery/Release Report Received	Completed		3/4/1992
Early Notice Letter(s)	Completed		3/28/1992
Initial Investigation / Federal Preliminary Assessment	Completed		9/9/1992
Early Notice Letter(s)	Completed		9/28/1992
Site Hazard Assessment/Federal Site Inspection	Completed	5/17/2001	8/24/2001
LUST - Report Received	Completed		7/17/2001
LUST - Report Received	Completed		7/17/2001
Hazardous Sites Listing/NPL	Completed		8/28/2001
Order/Decree/Amendment	In Process	2/1/2005	
Remedial Investigation and/or Feasibility Study	Completed	6/1/2005	3/29/2012
Interim Action - Construction	In Process	1/1/2014	
Order/Decree/Amendment	In Process	7/23/2019	