

Cleanup Site Details

Cleanup Site ID: 7093 Facility/Site ID: 53481373 UST ID: 11034 Site Page Site Documents View Map

Cleanup Site Name: Kaiser Aluminum & Chemical Corporation

Glossary

Cleanup Site ID: 7093

Alternate Names: Kaiser Aluminum, Kaiser Aluminum & Chemical Corporation, KAISER ALUMINUM & CHEMICAL INC, KAISER ALUMINUM & CHEMICAL INC UST 11034, KAISER ALUMINUM FABRICATED PRODUCTS, KAISER ALUMINUM FABRICATED PRODUCTS LLC, KAISER ALUMINUM TRENTWOOD, KAISER TRENTWOOD, TRENTWOOD PLANT

LOCATION

Address: 15000 E EUCLID AVE City: SPOKANE Zip Code: 99216 County: Spokane

Latitude: 47.68605 Longitude: -117.20560 WRIA: 57 Legislative District: 4 Congressional District: 5 TRS: 25N 44E 2

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Schmidt, Jeremy Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
KAISER-TRENTWOOD	Upland	Cleanup Started	EA	Eastern Region	Ecology-supervised or conducted
KAISER-TRENTWOOD	Upland	Cleanup Started	EA	Eastern Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	estriction Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	--------------------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	С	С				
Metals Priority Pollutants	С		S			
Petroleum Products-Unspecified		С	S			
Petroleum-Other	С					
Polychlorinated biPhenyls (PCB)	С	С	S			

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level

R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

S - Suspected

Activity	Status	Start Date	End Date/ Completion Date
Federal Site Inspection	Completed		12/19/1988
Early Notice Letter(s)	Completed		3/21/1991
Initial Investigation / Federal Preliminary Assessment	Completed		3/21/1991
LUST - Notification	Completed		4/29/1991

Toxics Cleanup Program Report Generated: 11/6/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
LUST - Notification	Completed		5/13/1991			
LUST - Report Received	Completed		6/3/1991			
Initial Investigation / Federal Preliminary Assessment	Completed		6/27/1991			
Early Notice Letter(s)	Completed		10/11/1991			
Site Discovery/Release Report Received	Completed		2/14/1992			
Initial Investigation / Federal Preliminary Assessment	Completed		3/4/1992			
Site Discovery/Release Report Received	Completed		3/4/1992			
Early Notice Letter(s)	Completed		3/28/1992			
Initial Investigation / Federal Preliminary Assessment	Completed		9/9/1992			
Early Notice Letter(s)	Completed		9/28/1992			
Site Hazard Assessment	Completed	5/17/2001	8/24/2001			
LUST - Report Received	Completed		7/17/2001			
LUST - Report Received	Completed		7/17/2001			
Hazardous Sites Listing	Completed		8/28/2001			
Order/Decree/Amendment	In Process	2/1/2005				
Remedial Investigation and/or Feasibility Study	Completed	6/1/2005	3/29/2012			
Interim Action - Construction	Completed	1/1/2014	7/1/2024			
Order/Decree/Amendment	In Process	7/23/2019				
Interim Action - O & M/Monitoring	In Process	7/1/2024				

Cleanup Site ID: 7093