

# Cleanup Site Details

Cleanup Site ID: 7093

Cleanup Site ID: 7093      Facility/Site ID: 53481373      UST ID: 11034      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Kaiser Aluminum & Chemical Corporation      [Glossary](#)

**Alternate Names:** Kaiser Aluminum, Kaiser Aluminum & Chemical Corporation, KAISER ALUMINUM & CHEMICAL INC, KAISER ALUMINUM & CHEMICAL INC UST 11034, KAISER ALUMINUM FABRICATED PRODUCTS, KAISER ALUMINUM FABRICATED PRODUCTS LLC, KAISER ALUMINUM TRENTWOOD, KAISER TRENTWOOD, TRENTWOOD PLANT

## LOCATION

**Address:** 15000 E EUCLID AVE      **City:** SPOKANE      **Zip Code:** 99216      **County:** Spokane  
**Latitude:** 47.68605      **Longitude:** -117.20560      **WRIA:** 57      **Legislative District:** 4      **Congressional District:** 5      **TRS:** 25N 44E 2

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** 2 - Moderate-High Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Schmidt, Jeremy      **Responsible Unit:** Eastern      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
KAISER-TRENTWOOD	Upland	Cleanup Started	EA	Eastern Region	Ecology-supervised or conducted
KAISER-TRENTWOOD	Upland	Cleanup Started	EA	Eastern Region	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	C	C				
Metals Priority Pollutants	C		S			
Petroleum Products-Unspecified		C	S			
Petroleum-Other	C					
Polychlorinated biPhenyls (PCB)	C	C	S			

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	10/19/1988	12/19/1988
Early Notice Letter(s)	Completed		3/21/1991
Initial Investigation / Federal Preliminary Assessment	Completed		3/21/1991
LUST - Notification	Completed		4/29/1991

# Cleanup Site Details

**Cleanup Site ID: 7093**

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
LUST - Notification	Completed		5/13/1991
LUST - Report Received	Completed		6/3/1991
Initial Investigation / Federal Preliminary Assessment	Completed		6/27/1991
Early Notice Letter(s)	Completed		10/11/1991
Site Discovery/Release Report Received	Completed		2/14/1992
Initial Investigation / Federal Preliminary Assessment	Completed		3/4/1992
Site Discovery/Release Report Received	Completed		3/4/1992
Early Notice Letter(s)	Completed		3/28/1992
Initial Investigation / Federal Preliminary Assessment	Completed		9/9/1992
Early Notice Letter(s)	Completed		9/28/1992
Site Hazard Assessment/Federal Site Inspection	Completed	5/17/2001	8/24/2001
LUST - Report Received	Completed		7/17/2001
LUST - Report Received	Completed		7/17/2001
Hazardous Sites Listing/NPL	Completed		8/28/2001
Order/Decree/Amendment	In Process	2/1/2005	
Remedial Investigation and/or Feasibility Study	Completed	6/1/2005	3/29/2012
Interim Action - Construction	Completed	1/1/2014	7/1/2024
Order/Decree/Amendment	In Process	7/23/2019	
Interim Action - O & M/Monitoring	In Process	7/1/2024	