DEPARTMENT OF ECOLOGY
State of Washington

Cleanup Site Details

Cleanup Site ID: 7093

Cleanup Site ID: 7093 **Facility/Site ID:** 53481373 **UST ID:** 11034 Site Page | Site Documents | View Map

Cleanup Site Name: Kaiser Aluminum & Chemical Corporation Glossary

Alternate Names: Kaiser Aluminum, Kaiser Aluminum & Chemical Corporation, KAISER ALUMINUM & CHEMICAL INC, KAISER ALUMINUM & CHEMICAL INC UST 11034, KAISER ALUMINUM FABRICATED PRODUCTS, KAISER ALUMINUM FABRICATED PRODUCTS LLC, KAISER ALUMINUM TRENTWOOD, KAISER TRENTWOOD, TRENTWOOD PLANT

LOCATION

Address: 15000 E EUCLID AVE **City:** SPOKANE **Zip Code:** 99216 **County:** Spokane

Latitude: 47.68605 **Longitude:** -117.20560 **WRIA:** 57 **Legislative District:** 4 **Congressional District:** 5 **TRS:** 25N 44E 2

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No

Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No

Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No

Site Manager: Schmidt, Jeremy **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
KAISER-TRENTWOOD	Upland	Cleanup Started	EA	Eastern Region	Ecology-supervised or conducted
KAISER-TRENTWOOD	Upland	Cleanup Started	EA	Eastern Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Conventional Contaminants, Inorganic	C	C				
Metals Priority Pollutants	C		S			
Petroleum Products-Unspecified		C	S			
Petroleum-Other	C					
Polychlorinated biPhenyls (PCB)	C	C	S			

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Federal Site Inspection	Completed		12/19/1988
Early Notice Letter(s)	Completed		3/21/1991
Initial Investigation / Federal Preliminary Assessment	Completed		3/21/1991
LUST - Notification	Completed		4/29/1991

Cleanup Site Details

Cleanup Site ID: 7093

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		5/13/1991
LUST - Report Received	Completed		6/3/1991
Initial Investigation / Federal Preliminary Assessment	Completed		6/27/1991
Early Notice Letter(s)	Completed		10/11/1991
Site Discovery/Release Report Received	Completed		2/14/1992
Initial Investigation / Federal Preliminary Assessment	Completed		3/4/1992
Site Discovery/Release Report Received	Completed		3/4/1992
Early Notice Letter(s)	Completed		3/28/1992
Initial Investigation / Federal Preliminary Assessment	Completed		9/9/1992
Early Notice Letter(s)	Completed		9/28/1992
Site Hazard Assessment	Completed	5/17/2001	8/24/2001
LUST - Report Received	Completed		7/17/2001
LUST - Report Received	Completed		7/17/2001
Hazardous Sites Listing	Completed		8/28/2001
Order/Decree/Amendment	In Process	2/1/2005	
Remedial Investigation and/or Feasibility Study	Completed	6/1/2005	3/29/2012
Interim Action - Construction	Completed	1/1/2014	7/1/2024
Order/Decree/Amendment	In Process	7/23/2019	
Interim Action - O & M/Monitoring	In Process	7/1/2024	