

Cleanup Site Details

Cleanup Site ID: 7128

Cleanup Site ID: 7128 Facility/Site ID: 78835792 UST ID: 5532 <u>Site Page</u> <u>Site Documents</u> <u>View Map</u>

Cleanup Site Name: L & L Exxon

Alternate Names: L & L Exxon, LEOS LINEUP & TIRES AUTO EXPRESS

LOCATION

Address: 1315 LEE BLVD City: RICHLAND Zip Code: 99352 County: Benton

Latitude: 46.27471 Longitude: -119.28051 WRIA: 40 Legislative District: 8 Congressional District: 4 TRS: 9N 28E 11

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Monahan, Mary Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
L & L EXXON	Upland	Cleanup Started	CE	Monahan, Mary	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording	Tax Parcel
• •	Iviedia	•		Number	County	

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene		С				
Petroleum-Diesel		С				
Petroleum-Gasoline	С	С				
Polycyclic Aromatic Hydrocarbons	С	С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/28/1989
LUST - Notification	Completed		8/28/1989
LUST - Report Received	Completed		8/28/1989
Site Discovery/Release Report Received	Completed		2/25/1999
LUST - Notification	Completed		2/25/1999
LUST - Site Assessment Report	Completed		4/1/1999
Initial Investigation / Federal Preliminary Assessment	Completed		5/24/1999

Toxics Cleanup Program Report Generated: 5/19/2024 Page 1 of 2



Early Notice Letter(s)

Cleanup Site Details

ECOLOGY State of Washington	Cleanup Site D	Site Details		Cleanup Site ID: 7128			
SITE ACTIVITIES							
Activity		Status	Start Date	End Date/ Completion Date			
Early Notice Letter(s)		Completed		11/28/2007			
Site Hazard Assessment/Federal Site Inspection		Completed	5/6/2010	8/17/2010			
Hazardous Sites Listing/NPL		Completed		8/18/2010			
LUST - Report Received		Completed		3/6/2013			
LUST - Report Received		Completed		4/10/2013			
LUST - Report Received		Completed		4/17/2013			
LUST - Report Received		Completed		6/7/2013			
LUST - Report Received		Completed		2/24/2014			
LUST - Report Received		Completed		3/27/2014			
Interim Action - Plan		Completed	9/1/2014	11/14/2014			
LUST - Report Received		Completed		3/2/2015			
LUST - Report Received		Completed		3/21/2016			
LUST - Report Received		Completed		3/21/2016			
LUST - Report Received		Completed		3/21/2016			

Completed

12/19/2017