

Cleanup Site Details

Cleanup Site ID: 7177

Cleanup Site ID: 7177 Facility/Site ID: 2099 UST ID: 10413 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Boeing Aerospace Building 18-42 [Glossary](#)

Alternate Names: Boeing A&M Space Center, Boeing A&M Space Center AST- 46 - Building 18-21, Boeing A&M Space Center Gun Club, Boeing Aerospace Bldg 18-03 Spill, Boeing Aerospace Bldg 18-67 Clearwater Property, Boeing Aerospace Bldg 7-133 Spill, Boeing Aerospace Building 18-41, Boeing Aerospace Building 18-42, Boeing Kent Space Center, BOEING SPACE CENTER, Boeing Space Center AST-46 Bldg 18-21, BOEING SPACE CENTER TANK ENGINE RELEASE

LOCATION

Address: 20403 68TH AVE S **City:** KENT **Zip Code:** 98032 **County:** King
Latitude: 47.41938 **Longitude:** -122.24971 **WRIA:** 9 **Legislative District:** 33 **Congressional District:** 9 **TRS:** 22N 4E 2

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Northwest Region **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Boeing Aerospace Building 18-42	Upland	Cleanup Started	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	B				
Lead	C					
Petroleum-Diesel	C	B				
Petroleum-Gasoline	C	B				
Petroleum-Other	C	B				
Polychlorinated biPhenyls (PCB)	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		7/9/1993
Site Discovery/Release Report Received	Completed		7/9/1993
LUST - Report Received	Completed		11/29/1993

Cleanup Site Details

Cleanup Site ID: 7177

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		11/29/1993
Initial Investigation / Federal Preliminary Assessment	Completed		8/8/2011
Early Notice Letter(s)	Completed		4/16/2013