

Cleanup Site Details

Cleanup Site ID: 723 Facility/Site ID: 1385 UST ID: 1086 Site Page Site Documents View Map

Cleanup Site ID: 723

Cleanup Site Name: Cascade Pole Inc McFarland

Alternate Names: CASCADE POLE CO, CASCADE POLE INC MCFARLAND, CASCADE POLE OLYMPIA

LOCATION

Address: 1100 WASHINGTON ST City: OLYMPIA Zip Code: 98501 County: Thurston

Latitude: 47.05753 Longitude: -122.90088 WRIA: 13 Legislative District: 22 Congressional District: 10 TRS: 18N 2W 42

DETAIL

Status: Construction Complete- NFA Received? No Is PSI site? Yes

Performance Monitoring

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Smith, Sandy Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CASCADE POLE CO	Sediment	Cleanup Complete-Active O&M/Monitoring ongoing	sw	Smith, Sandy	Ecology-supervised or conducted
CASCADE POLE CO	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	sw	Smith, Sandy	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Base/Neutral/Acid Organics	С	С					
Dioxins/Furans	С	С	С	R			
Metals Priority Pollutants	С	С					
Petroleum Products-Unspecified	С	С	С				
Phenolic Compounds	С	С	С				
Polycyclic Aromatic Hydrocarbons	С	С	С	R			

Key

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA S - Suspected R - Remediated RB

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process	10/17/1989	
Site Hazard Assessment	Completed	5/1/1990	9/10/1990
Order/Decree/Amendment	In Process	5/28/1990	

Toxics Cleanup Program Report Generated: 7/25/2025 Page 1 of 3



Cleanup Site Details

Cleanup Site ID: 723

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action	Completed	5/29/1990	6/30/1997
Remedial Investigation and/or Feasibility Study	Completed	5/29/1990	12/31/1993
Remedial Investigation and/or Feasibility Study	Completed	5/29/1990	12/31/1993
Interim Action	Completed	5/29/1990	12/1/2000
Interim Action	Completed	6/11/1990	12/15/1990
Interim Action	Completed	6/12/1990	12/31/1992
Order/Decree/Amendment	In Process	6/13/1990	
Hazardous Sites Listing	Completed		9/10/1990
Order/Decree/Amendment	In Process	2/22/1991	
Order/Decree/Amendment	In Process	11/12/1992	
Interim Action	Completed	10/1/1993	2/28/2002
Interim Action	Canceled	6/1/1995	12/1/1997
Interim Action	Completed	6/1/1995	6/1/1998
Interim Action	Completed	6/1/1995	6/1/1997
Order/Decree/Amendment	In Process	8/8/1996	
Cleanup Action - Engineering Design	Completed	9/1/1996	12/1/2001
Cleanup - Construction	Completed	9/1/1996	12/1/2002
O & M	In Process	7/1/1997	
Order/Decree/Amendment	In Process	4/24/1998	
Cleanup Action Plan	Completed	10/1/1999	6/30/2000
Cleanup Action Plan	Completed	1/1/2000	1/1/2002
Order/Decree/Amendment	In Process	4/11/2000	
Order/Decree/Amendment	In Process	7/3/2004	
Site Discovery/Release Report Received	Completed		11/18/2005
Order/Decree/Amendment	In Process	6/21/2010	
Monitoring	Completed	4/1/2011	3/28/2012
Monitoring	Completed	4/1/2012	3/31/2013
Monitoring	Completed	4/30/2013	3/30/2014
Monitoring	Completed	3/30/2014	3/30/2015
Monitoring	Completed	4/1/2015	3/1/2016
Monitoring	Completed		6/30/2016
Monitoring	Completed	7/1/2017	6/30/2018
Monitoring	Completed	8/1/2017	8/31/2017
Monitoring	Completed	10/2/2017	10/17/2017
Cleanup - Performance Monitoring	Completed	4/2/2018	3/4/2019
Toxics Cleanup Program Report Generated: 7/25/2025			Page 2 of 3



Cleanup Site Details

SITE ACTIVITIES			
Activity	Status	Start Date End Date/ Completion Date	
Monitoring	Completed	7/1/2018	12/31/2018

Cleanup Site ID: 723