

Cleanup Site Details

Cleanup Site ID: 723
Cleanup Site ID: 723 **Facility/Site ID:** 1385 **UST ID:** 1086 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Cascade Pole Inc McFarland [Glossary](#)
Alternate Names: CASCADE POLE CO, CASCADE POLE INC MCFARLAND, CASCADE POLE OLYMPIA

LOCATION
Address: 1100 WASHINGTON ST **City:** OLYMPIA **Zip Code:** 98501 **County:** Thurston
Latitude: 47.05753 **Longitude:** -122.90088 **WRIA:** 13 **Legislative District:** 22 **Congressional District:** 10 **TRS:** 18N 2W 42

DETAIL
Status: Construction Complete-Performance Monitoring **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Smith, Sandy **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CASCADE POLE CO	Sediment	Cleanup Complete-Active O&M/Monitoring ongoing	SW	Smith, Sandy	Ecology-supervised or conducted
CASCADE POLE CO	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	SW	Smith, Sandy	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C	C				
Dioxins/Furans	C	C	C	R		
Metals Priority Pollutants	C	C				
Petroleum Products-Unspecified	C	C	C			
Phenolic Compounds	C	C	C			
Polycyclic Aromatic Hydrocarbons	C	C	C	R		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	In Process	10/17/1989	
Site Hazard Assessment/Federal Site Inspection	Completed	5/1/1990	9/10/1990
Order/Decree/Amendment	In Process	5/28/1990	

Cleanup Site Details

Cleanup Site ID: 723

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action	Completed	5/29/1990	6/30/1997
Remedial Investigation and/or Feasibility Study	Completed	5/29/1990	12/31/1993
Remedial Investigation and/or Feasibility Study	Completed	5/29/1990	12/31/1993
Interim Action	Completed	5/29/1990	12/1/2000
Interim Action	Completed	6/11/1990	12/15/1990
Interim Action	Completed	6/12/1990	12/31/1992
Order/Decree/Amendment	In Process	6/13/1990	
Hazardous Sites Listing/NPL	Completed		9/10/1990
Order/Decree/Amendment	In Process	2/22/1991	
Order/Decree/Amendment	In Process	11/12/1992	
Interim Action	Completed	10/1/1993	2/28/2002
Interim Action	Canceled	6/1/1995	12/1/1997
Interim Action	Completed	6/1/1995	6/1/1998
Interim Action	Completed	6/1/1995	6/1/1997
Order/Decree/Amendment	In Process	8/8/1996	
Cleanup Action - Engineering Design	Completed	9/1/1996	12/1/2001
Cleanup - Construction	Completed	9/1/1996	12/1/2002
O & M	In Process	7/1/1997	
Order/Decree/Amendment	In Process	4/24/1998	
Cleanup Action Plan	Completed	10/1/1999	6/30/2000
Cleanup Action Plan	Completed	1/1/2000	1/1/2002
Order/Decree/Amendment	In Process	4/11/2000	
Order/Decree/Amendment	In Process	7/3/2004	
Site Discovery/Release Report Received	Completed		11/18/2005
Order/Decree/Amendment	In Process	6/21/2010	
Monitoring	Completed	4/1/2011	3/28/2012
Monitoring	Completed	4/1/2012	3/31/2013
Monitoring	Completed	4/30/2013	3/30/2014
Monitoring	Completed	3/30/2014	3/30/2015
Monitoring	Completed	4/1/2015	3/1/2016
Monitoring	Completed		6/30/2016
Monitoring	Completed	7/1/2017	6/30/2018
Monitoring	Completed	8/1/2017	8/31/2017
Monitoring	Completed	10/2/2017	10/17/2017
Cleanup - Performance Monitoring	Completed	4/2/2018	3/4/2019

Cleanup Site Details

Cleanup Site ID: 723

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Monitoring	Completed	7/1/2018	12/31/2018