

# Cleanup Site Details

Cleanup Site ID: 7520

Cleanup Site ID: 7520 Facility/Site ID: 3112128 UST ID: 5272 Site Page Site Documents View Map

Cleanup Site Name: ARCO 5377

Alternate Names: AM PM, ARCO 05377, Arco 5377, ARCO 5377 PSI 5507, ARCO 5377 PSI 5507, Arco 7025

LOCATION

Address: 13131 BOTHELL EVERETT HWY City: EVERETT Zip Code: 98208 County: Snohomish

Latitude: 47.87864 Longitude: -122.20626 WRIA: 8 Legislative District: 44 Congressional District: 1 TRS: 28N 5E 29

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: PLIA Responsible Unit: Pollution Liability Ins Agcy Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ARCO STATION 5377	Upland	Cleanup Started	PLIA	PLIA	PLIA Petroleum Technical

### **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction	Restrictions/Requirements	Date	Recording	Recording	Tax Parcel
	Media	110001101101110111011101110		Number	County	

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	С	С				
Lead	С	С				
Methyl tertiary-butyl ether	С	С				
Non-Halogenated Solvents	С	С				
Petroleum-Gasoline	С	С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

#### SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/14/2003
LUST - Report Received	Completed		7/3/2003
LUST - Report Received	Completed		10/5/2004
LUST - Report Received	Completed		1/10/2005
LUST - Report Received	Completed		1/21/2005
LUST - Report Received	Completed		8/31/2005

Toxics Cleanup Program Report Generated: 10/16/2025 Page 1 of 2



# Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
LUST - Report Received	Completed		2/27/2006			
LUST - Report Received	Completed		8/24/2006			
LUST - Report Received	Completed		3/19/2007			
LUST - Report Received	Completed		10/30/2007			
LUST - Report Received	Completed		6/11/2009			
LUST - Report Received	Completed		2/22/2010			
LUST - Report Received	Completed		12/13/2010			
LUST - Report Received	Completed		3/18/2011			
LUST - Report Received	Completed		5/2/2011			
Non-LUST Ind Report Received	Completed		5/26/2011			
Non-LUST Ind Report Received	Completed		5/26/2011			
LUST - Report Received	Completed		5/26/2011			
LUST - Report Received	Completed		5/26/2011			
LUST - Report Received	Completed		7/5/2012			
VCP Receipt of Plan or Report	Completed		7/6/2012			
LUST - Report Received	Completed		4/1/2013			
LUST - Report Received	Completed		6/23/2015			
LUST - Report Received	Completed		6/23/2015			
LUST - Report Received	Completed		4/26/2016			
LUST - Report Received	Completed		5/17/2016			
LUST - Report Received	Completed		10/25/2016			
LUST - Report Received	Completed		3/27/2017			
LUST - Report Received	Completed		4/2/2018			
VCP Status Request	Completed	8/24/2018	11/9/2018			

Cleanup Site ID: 7520