

# Cleanup Site Details

Cleanup Site ID: 7520

Cleanup Site ID: 7520      Facility/Site ID: 3112128      UST ID: 5272      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: ARCO 5377      [Glossary](#)

Alternate Names: AM PM, ARCO 05377, Arco 5377, ARCO 5377 PSI 5507, ARCO 5377 PSI 5507, Arco 7025

## LOCATION

**Address:** 13131 BOTHELL EVERETT HWY      **City:** EVERETT      **Zip Code:** 98208      **County:** Snohomish  
**Latitude:** 47.87864      **Longitude:** -122.20626      **WRIA:** 8      **Legislative District:** 44      **Congressional District:** 1      **TRS:** 28N 5E 29

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** N/A      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** PLIA      **Responsible Unit:** Pollution Liability Ins Agcy      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ARCO STATION 5377	Upland	Cleanup Started	PLIA	PLIA	PLIA Petroleum Technical

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Lead	C	C				
Methyl tertiary-butyl ether	C	C				
Non-Halogenated Solvents	C	C				
Petroleum-Gasoline	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/14/2003
LUST - Report Received	Completed		7/3/2003
LUST - Report Received	Completed		10/5/2004
LUST - Report Received	Completed		1/10/2005
LUST - Report Received	Completed		1/21/2005
LUST - Report Received	Completed		8/31/2005

# Cleanup Site Details

Cleanup Site ID: 7520

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		2/27/2006
LUST - Report Received	Completed		8/24/2006
LUST - Report Received	Completed		3/19/2007
LUST - Report Received	Completed		10/30/2007
LUST - Report Received	Completed		6/11/2009
LUST - Report Received	Completed		2/22/2010
LUST - Report Received	Completed		12/13/2010
LUST - Report Received	Completed		3/18/2011
LUST - Report Received	Completed		5/2/2011
Non-LUST Ind Report Received	Completed		5/26/2011
Non-LUST Ind Report Received	Completed		5/26/2011
LUST - Report Received	Completed		5/26/2011
LUST - Report Received	Completed		5/26/2011
LUST - Report Received	Completed		7/5/2012
VCP Receipt of Plan or Report	Completed		7/6/2012
LUST - Report Received	Completed		4/1/2013
LUST - Report Received	Completed		6/23/2015
LUST - Report Received	Completed		6/23/2015
LUST - Report Received	Completed		4/26/2016
LUST - Report Received	Completed		5/17/2016
LUST - Report Received	Completed		10/25/2016
LUST - Report Received	Completed		3/27/2017
LUST - Report Received	Completed		4/2/2018
VCP Status Request	Completed	8/24/2018	11/9/2018