

Cleanup Site Details

Cleanup Site ID: 7859

Cleanup Site ID: 7859	Facility/Site ID: 9872319	UST ID: 9096	Site Page	Site Documents	View Map
Cleanup Site Name: Weldco Beales					Glossary
Alternate Names: Weldco Beales, Weldco Beales Garrett St, Weldco Beales Inc Plant 2, WELDCO WA INC, WELDCO WA INC UST 9096					

LOCATION

Address: 1891 GARRETT ST			City: ENUMCLAW	Zip Code: 98022	County: King
Latitude: 47.20324	Longitude: -121.98447	WRIA: 9	Legislative District: 31	Congressional District: 8	TRS:

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 12/30/2016	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: Site Hazard Assessment	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Weldco Beales	Upland	No Further Action Required	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Other Non-Halogenated Organics	RB					
Petroleum-Diesel	RB					
Petroleum-Gasoline	RB	RB				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/12/1991
LUST - Report Received	Completed		12/30/1991
Petroleum Impacts to Groundwater Model Remedies	Completed		8/15/2016
Site Hazard Assessment	Completed	8/24/2016	12/30/2016
Site Status Changed to NFA	Completed		12/30/2016