

## Cleanup Site Details

Cleanup Site ID: 7859 Facility/Site ID: 9872319 UST ID: 9096 Site Page Site Documents View Map

Cleanup Site ID: 7859

Cleanup Site Name: Weldco Beales Glossary

Alternate Names: Weldco Beales, Weldco Beales Garrett St, Weldco Beales Inc Plant 2, WELDCO WA INC, WELDCO WA INC UST 9096

LOCATION

Address: 1891 GARRETT ST City: ENUMCLAW Zip Code: 98022 County: King

Latitude: 47.20324 Longitude: -121.98447 WRIA: 9 Legislative District: 31 Congressional District: 8 TRS:

**DETAIL** 

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 12/30/2016 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Site Hazard Assessment Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

 
 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Weldco Beales
 Upland
 No Further Action Required
 NW
 Northwest Region
 Independent Action

**ACTIVE INSTITUTIONAL CONTROLS** 

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Other Non-Halogenated Organics	RB					
Petroleum-Diesel	RB					
Petroleum-Gasoline	RB	RB				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/12/1991
LUST - Report Received	Completed		12/30/1991
Petroleum Impacts to Groundwater Model Remedies	Completed		8/15/2016
Site Hazard Assessment	Completed	8/24/2016	12/30/2016
Site Status Changed to NFA	Completed		12/30/2016

Toxics Cleanup Program Report Generated: 11/18/2025 Page 1 of 1