

Cleanup Site Details

Cleanup Site ID: 788

Cleanup Site ID: 788 Facility/Site ID: 2065 **UST ID: 6609** Site Page **Site Documents** View Map

Cleanup Site Name: Pacific Car & Foundry Co **Glossary**

Alternate Names: ACTIVE USA INC, DALLAS & MAVIS FORWARDING TRUCK DEC, PACCAR DEFENSE SYSTEMS, PACCAR INC RENTON SITE, PACIFIC CAR & FOUNDRY CO, PACIFIC CAR & FOUNDRY CO., PACIFIC CAR & FOUNDRY COMPANY, PACIFIC CAR AND FOUNDRY

COMPANY

LOCATION

Address: 1400 N 4TH ST City: RENTON **Zip Code: 98057** County: King

Latitude: 47.49102 Longitude: -122.19790 WRIA: 8 Legislative District: 37 Congressional District: 9 TRS:

DETAIL

Status: Construction Complete-NFA Received? No

Is PSI site? No Performance Monitoring

Statute: MTCA NFA Date: N/A **Current VCP?** No Past VCP? No

Site Rank: 0 - NPL Site (Fed HRS Score) NFA Reason: N/A **Brownfield?** No

Site Manager: DeBoer, Chris Responsible Unit: Northwest **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Pacific Car & Foundry Co	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	NW	DeBoer, Chris	Federal-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Ongoing Maintenance of Remedy	9/1/1994	9409010221	King	7223000010
Amended Environmental Covenant	Groundwater, Soil	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Restrict Access, Prohibit Soil Disturbance, Ongoing Maintenance of Remedy	1/17/2023	20230117000650	King	7223000010

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the Environmental Covenants Registry List.

AFFECTED MEDIA & CONTAMINANTS

MEDIA							
Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
С							
С	С						
С							
С	С						
С							
С							
С							
С							
С							
	C C C C C C C	C C C C C C C C C C C C C C C C C C C	Soil Groundwater Surface Water C C C C C C C C C C C C C C C C C C	Soil Groundwater Surface Water Sediment C C C C C C C C C C C C C C C C C C	Soil Groundwater Surface Water Sediment Air C C C C C C C C C C C C C C C C C C		

Toxics Cleanup Program Report Generated: 5/2/2024 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 788

Key: B - Below Cleanup Level S - Suspected

C - Confirmed Above Cleanup Level R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date	
Remedial Investigation and/or Feasibility Study	Completed	7/1/1988	8/30/1991	
Order/Decree/Amendment	In Process	11/7/1988		
Cleanup Action Plan	Completed	6/15/1990	9/15/1991	
Site Hazard Assessment/Federal Site Inspection	Completed		9/10/1990	
Hazardous Sites Listing/NPL	Completed		9/10/1991	
Cleanup - Construction	Completed	9/15/1991	11/8/1997	
O & M	In Process	11/8/1997		
Periodic Review	Completed	10/1/2009	11/23/2009	
Periodic Review	Completed	3/1/2014	7/1/2014	
Periodic Review	Completed	7/1/2020	11/29/2021	
Periodic Review	Planned	11/29/2026		

Page 2 of 2 **Toxics Cleanup Program** Report Generated: 5/2/2024