

Cleanup Site Details

Cleanup Site ID: 7906

Cleanup Site ID: 7906 **Facility/Site ID:** 11687976 **UST ID:** 5294 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Bothell Former Hertz [Glossary](#)
Alternate Names: AA RENTALS OF BOTHELL INC, Aarenco, Bothell Former Hertz

LOCATION

Address: 18030 BOTHELL WAY NE **City:** BOTHELL **Zip Code:** 98011 **County:** King
Latitude: 47.75879 **Longitude:** -122.20892 **WRIA:** 8 **Legislative District:** 1 **Congressional District:** 1 **TRS:** 26N 5E 7

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Becker, Sunny **Responsible Unit:** Northwest **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Bothell Former Hertz	Upland	Cleanup Started	NW	Becker, Sunny	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Ongoing Maintenance of Remedy, Control Vapor/Gas, Maintain/Protect Monitoring System	5/13/2020	20200513000357	King	9457200050, 2374200065
Environmental Covenant	Groundwater	Restrict All Ground Water Extraction/Well Installation, Ongoing Maintenance of Remedy, Control Vapor/Gas, Maintain/Protect Monitoring System	5/13/2020	20200513000357	King	9457200015
Other Upland Instrument	Groundwater, Soil	Restrict All Ground Water Extraction/Well Installation, Restrict Domestic Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Ongoing Maintenance of Remedy, Maintain/Protect Monitoring System	7/9/2021		King	

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	B	C				
Conventional Contaminants, Organic	RB	C				
Halogenated Solvents		C				
Petroleum-Diesel	RB	RA				
Petroleum-Gasoline	RB	RB				
Petroleum-Other	RB	RA				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 7906

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/5/1993
LUST - Report Received	Completed		5/14/1993
LUST - Report Received	Completed		9/10/1993
LUST - Report Received	Completed		10/2/2001
Site Discovery/Release Report Received	Completed		1/4/2009
Order/Decree/Amendment	Completed	6/15/2010	1/31/2018
Initial Investigation / Federal Preliminary Assessment	Completed		7/20/2010
Early Notice Letter(s)	Completed		8/13/2010
Interim Action - Construction	Completed	9/8/2010	9/22/2010
Remedial Investigation and/or FS Work Plan	Completed	6/9/2011	1/11/2013
Interim Action - Construction	Completed	3/6/2012	3/8/2012
Interim Action - Construction	Completed	3/6/2013	3/6/2019
Remedial Investigation and/or Feasibility Study	Completed	8/4/2015	8/10/2017
Cleanup Action Plan	Completed	6/12/2017	5/29/2018
Order/Decree/Amendment	In Process	8/30/2017	
Periodic Review	Planned	5/13/2025	