

Cleanup Site Details

Cleanup Site ID: 793

Cleanup Site ID: 793 Facility/Site ID: 2126 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)
 Cleanup Site Name: Haller Lake Landfill [Glossary](#)
 Alternate Names: HALLER LAKE LANDFILL

LOCATION

Address: N 125TH ST City: SEATTLE Zip Code: 98133 County: King
 Latitude: 47.71961 Longitude: -122.34449 WRIA: 8 Legislative District: 46 Congressional District: 7 TRS: 26N 4E 19

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
 Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
 Site Rank: N/A NFA Reason: N/A Brownfield? No
 Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Haller Lake Landfill	Upland	Awaiting Cleanup	NW	Northwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	S	S	S		S	
Conventional Contaminants, Organic	S	S	S		S	

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988