

# Cleanup Site Details

Cleanup Site ID: 798

Cleanup Site ID: 798      Facility/Site ID: 2667      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Olympic Pipe Line Co Allen Station      [Glossary](#)

Alternate Names: Allen Pump Station, Olympic Pipe Line Co Allen Station, OLYMPIC PIPELINE CO ALLEN STATION

## LOCATION

Address: 16471 SR 20 / 16292 OVENELL RD      City: MOUNT VERNON      Zip Code: 98273      County: Skagit  
Latitude: 48.45568      Longitude: -122.39024      WRIA: 3      Legislative District: 10      Congressional District: 2      TRS: 34N 3E 11

## DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No      Past VCP? No
Site Rank: 1 - Highest Assessed Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Olympic Pipe Line Co Allen Station	Upland	Cleanup Started	NW	Northwest Region	Independent Action

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	C	C	S			

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Site Hazard Assessment/Federal Site Inspection	Completed	2/18/2010	8/17/2010
Non-LUST Ind Report Received	Completed		5/18/2010
Hazardous Sites Listing/NPL	Completed		8/17/2010
Non-LUST Ind Report Received	Completed		9/29/2010
Non-LUST Ind Report Received	Completed		3/23/2011
Non-LUST Ind Report Received	Completed		7/22/2011
Non-LUST Ind Report Received	Completed		12/28/2011
Non-LUST Ind Report Received	Completed		9/6/2012
Non-LUST Ind Report Received	Completed		8/19/2013

# Cleanup Site Details

Cleanup Site ID: 798

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		10/24/2013
Non-LUST Ind Report Received	Completed		4/4/2014
Non-LUST Ind Report Received	Completed		8/18/2014
Non-LUST Ind Report Received	Completed		4/14/2015
Non-LUST Ind Report Received	Completed		5/21/2015
Non-LUST Ind Report Received	Completed		7/24/2015
Non-LUST Ind Report Received	Completed		2/18/2016
Non-LUST Ind Report Received	Completed		9/13/2016
Non-LUST Ind Report Received	Completed		3/5/2018
Non-LUST Ind Report Received	Completed		7/9/2018
Non-LUST Ind Report Received	Completed		10/30/2018
Non-LUST Ind Report Received	Completed		2/19/2019
Non-LUST Ind Report Received	Completed		8/15/2019
Non-LUST Ind Report Received	Completed		1/21/2020
Non-LUST Ind Report Received	Completed		8/17/2020
Non-LUST Ind Report Received	Completed		2/11/2021
Non-LUST Ind Report Received	Completed		3/16/2021
Non-LUST Ind Report Received	Completed		8/20/2021
Non-LUST Ind Report Received	Completed		3/3/2022
Non-LUST Ind Report Received	Completed		7/29/2022
Non-LUST Ind Report Received	Completed		2/8/2023
Non-LUST Ind Report Received	Completed		7/26/2023
Non-LUST Ind Report Received	Completed		2/16/2024
Non-LUST Ind Report Received	Completed		8/5/2024
Non-LUST Ind Report Received	Completed		1/27/2025