

Cleanup Site Details

Cleanup Site ID: 798

Cleanup Site ID: 798 Facility/Site ID: 2667 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Olympic Pipe Line Co Allen Station [Glossary](#)

Alternate Names: Allen Pump Station, Olympic Pipe Line Co Allen Station, OLYMPIC PIPELINE CO ALLEN STATION

LOCATION

Address: 16471 SR 20 / 16292 OVENELL RD City: MOUNT VERNON Zip Code: 98273 County: Skagit
Latitude: 48.45568 Longitude: -122.39024 WRIA: 3 Legislative District: 10 Congressional District: 2 TRS: 34N 3E 11

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Olympic Pipe Line Co Allen Station	Upland	Cleanup Started	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	C	C	S			

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Site Hazard Assessment	Completed	2/18/2010	8/17/2010
Non-LUST Ind Report Received	Completed		5/18/2010
Hazardous Sites Listing	Completed		8/17/2010
Non-LUST Ind Report Received	Completed		9/29/2010
Non-LUST Ind Report Received	Completed		3/23/2011
Non-LUST Ind Report Received	Completed		7/22/2011
Non-LUST Ind Report Received	Completed		12/28/2011
Non-LUST Ind Report Received	Completed		9/6/2012
Non-LUST Ind Report Received	Completed		8/19/2013

Cleanup Site Details

Cleanup Site ID: 798

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		10/24/2013
Non-LUST Ind Report Received	Completed		4/4/2014
Non-LUST Ind Report Received	Completed		8/18/2014
Non-LUST Ind Report Received	Completed		4/14/2015
Non-LUST Ind Report Received	Completed		5/21/2015
Non-LUST Ind Report Received	Completed		7/24/2015
Non-LUST Ind Report Received	Completed		2/18/2016
Non-LUST Ind Report Received	Completed		9/13/2016
Non-LUST Ind Report Received	Completed		3/5/2018
Non-LUST Ind Report Received	Completed		7/9/2018
Non-LUST Ind Report Received	Completed		10/30/2018
Non-LUST Ind Report Received	Completed		2/19/2019
Non-LUST Ind Report Received	Completed		8/15/2019
Non-LUST Ind Report Received	Completed		1/21/2020
Non-LUST Ind Report Received	Completed		8/17/2020
Non-LUST Ind Report Received	Completed		2/11/2021
Non-LUST Ind Report Received	Completed		3/16/2021
Non-LUST Ind Report Received	Completed		8/20/2021
Non-LUST Ind Report Received	Completed		3/3/2022
Non-LUST Ind Report Received	Completed		7/29/2022
Non-LUST Ind Report Received	Completed		2/8/2023
Non-LUST Ind Report Received	Completed		7/26/2023
Non-LUST Ind Report Received	Completed		2/16/2024
Non-LUST Ind Report Received	Completed		8/5/2024
Non-LUST Ind Report Received	Completed		1/27/2025