

## Cleanup Site Details

Cleanup Site ID: 7996

Cleanup Site ID: 7996 Facility/Site ID: 13693544 **UST ID: 200438** Site Page **Site Documents** View Map

Cleanup Site Name: JACKS AUTO REPAIR **Glossary** 

Alternate Names: 1400-1408 Bethel Street NE, JACKS AUTO REPAIR

LOCATION

Address: 1400 BETHEL ST NE City: OLYMPIA **Zip Code:** 98506 County: Thurston

Latitude: 47.05732 Longitude: -122.88462 **WRIA:** 13 Legislative District: 22 Congressional District: 10 TRS: 18N 2W 42

**DETAIL** 

NFA Received? Is PSI site? Status: No Yes Cleanup Started

MTCA NFA Date: Current VCP? Past VCP? No Statute: N/A No

NFA Reason: Site Rank: 5 - Lowest Assessed Risk N/A Brownfield?

Site Manager: Malte, Dean Responsible Unit: Southwest **Active Institutional Control?** No

**CLEANUP UNITS** 

Resp **Cleanup Unit Name Unit Type Unit Status Unit Manager Current Process** Unit JACKS AUTO REPAIR SW Upland Cleanup Started Malte, Dean Independent Action

**ACTIVE INSTITUTIONAL CONTROLS** 

Restriction Recording Recording **Instrument Type** Tax Parcel Restrictions/Requirements Date Media Number County

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene	С	С			S		
Lead	В						
Other Non-Halogenated Organics	С	С			S		
Petroleum-Diesel	С	S			S		
Petroleum-Gasoline	С	С			S		
Petroleum-Other	С	S					
Polychlorinated biPhenyls (PCB)	С						
Polycyclic Aromatic Hydrocarbons		С					

**Key:** B - Below Cleanup Level C - Confirmed Above Cleanup Level

R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

S - Suspected

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		10/2/1990
LUST - Report Received	Completed		4/3/1991
Site Discovery/Release Report Received	Completed		10/2/1992

**Toxics Cleanup Program** Report Generated: 5/10/2025 Page 1 of 2



## Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Initial Investigation / Federal Preliminary Assessment	Completed		1/5/2012			
Early Notice Letter(s)	Completed		3/7/2013			
Site Hazard Assessment/Federal Site Inspection	Completed	12/4/2013	12/27/2013			
Hazardous Sites Listing/NPL	Completed		12/27/2013			
Petroleum Eligibility Letter	Completed		5/10/2021			
LUST - Site Assessment Report	Completed		10/29/2021			

Cleanup Site ID: 7996