

Cleanup Site Details

Cleanup Site ID: 7996

Facility/Site ID: 13693544 Cleanup Site ID: 7996 **UST ID: 200438** Site Page **Site Documents** View Map

Cleanup Site Name: JACKS AUTO REPAIR **Glossary**

Alternate Names: 1400-1408 Bethel Street NE, JACKS AUTO REPAIR

LOCATION

Address: 1400 BETHEL ST NE City: OLYMPIA **Zip Code:** 98506 County: Thurston

Latitude: 47.05732 Longitude: -122.88462 **WRIA**: 13 Legislative District: 22 Congressional District: 10 TRS: 18N 2W 42

DETAIL

NFA Received? No Is PSI site? Status: Yes Cleanup Started

MTCA NFA Date: Current VCP? No Past VCP? No Statute: N/A

NFA Reason: Site Rank: 5 - Lowest Assessed Risk N/A Brownfield?

Site Manager: Malte, Dean Responsible Unit: Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
JACKS AUTO REPAIR	Upland	Cleanup Started	SW	Malte, Dean	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene	С	С			S		
Lead	В						
Other Non-Halogenated Organics	С	С			S		
Petroleum-Diesel	С	S			S		
Petroleum-Gasoline	С	С			S		
Petroleum-Other	С	S					
Polychlorinated biPhenyls (PCB)	С						
Polycyclic Aromatic Hydrocarbons		С					

Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		10/2/1990
LUST - Report Received	Completed		4/3/1991
Site Discovery/Release Report Received	Completed		10/2/1992

Toxics Cleanup Program Report Generated: 10/28/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Initial Investigation / Federal Preliminary Assessment	Completed		1/5/2012			
Early Notice Letter(s)	Completed		3/7/2013			
Site Hazard Assessment	Completed	12/4/2013	12/27/2013			
Hazardous Sites Listing	Completed		12/27/2013			
Petroleum Eligibility Letter	Completed		5/10/2021			
LUST - Site Assessment Report	Completed		10/29/2021			

Cleanup Site ID: 7996