

Cleanup Site Details

Cleanup Site ID: 8026

Cleanup Site ID: 8026 Facility/Site ID: 14239975 UST ID: 5749 Site Page Site Documents View Map

Cleanup Site Name: Cirkle K 1467

Alternate Names: CIRCLE K 01467, CIRCLE K 1467, Cirkle K 1467

LOCATION

Address: 15059 1ST AVE S City: BURIEN Zip Code: 98148 County: King

Latitude: 47.46716 Longitude: -122.33423 WRIA: 9 Legislative District: 34 Congressional District: 7 TRS: 23N 4E 19

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 2/2/2012 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cirkle K 1467

Unit Type

Unit Status

Resp
Unit Manager

Current Process

NW Northwest Region

Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

		MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene	RB						
Petroleum-Gasoline	RB						
Petroleum-Other	RB						

Key:

B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/5/1990
Site Discovery/Release Report Received	Completed		2/5/1990
LUST - Report Received	Completed		6/21/1990
Initial Investigation / Federal Preliminary Assessment	Completed		2/22/2011
Site Status Changed to NFA	Completed		2/2/2012

Toxics Cleanup Program Report Generated: 5/11/2025 Page 1 of 1