

# Cleanup Site Details

Cleanup Site ID: 823

Cleanup Site ID: 823      Facility/Site ID: 2129      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Salmon Bay Center      [Glossary](#)

Alternate Names: CD STIMSON CO, HONEYWELL, INC., Salmon Bay Center, STIMSON MARINA

## LOCATION

Address: 5245-5423 SHILSHOLE AVE NW      City: SEATTLE      Zip Code: 98107      County: King  
Latitude: 47.66651      Longitude: -122.38496      WRIA: 8      Legislative District: 36      Congressional District: 7      TRS: 25N 3E 11

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? Yes  
Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
Site Manager: Northwest Region      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Salmon Bay Center	Sediment	Awaiting Cleanup	NW	Bardy, Louise	Independent Action
Salmon Bay Center	Upland	Cleanup Started	NW	Northwest Region	Independent Action

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	S	C		S		
Conventional Contaminants, Inorganic				C		
Lead	S	B		S		
Mercury				S		
Metals - Other				S		
Metals Priority Pollutants			R			
Non-Halogenated Solvents			R			
Organotins			S	C		
Other Non-Halogenated Organics					C	
Petroleum Products-Unspecified			R			
Petroleum-Diesel	B	B				
Petroleum-Other	B	B				
Polycyclic Aromatic Hydrocarbons	C	B		C		

# Cleanup Site Details

Cleanup Site ID: 823

**Key:**

B - Below Cleanup Level

C - Confirmed Above Cleanup Level

RA - Remediated-Above

S - Suspected

R - Remediated

RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Cleanup Action	Completed	11/6/1997	5/1/1999
Initial Investigation / Federal Preliminary Assessment	Completed		7/21/1998
Site Status Changed to NFA	Completed		5/1/1999
VCP Status Request	Completed	4/10/2006	4/17/2006
Reopen Site	Completed		6/7/2006
VCP Receipt of Plan or Report	Completed		7/6/2011
VCP Receipt of Plan or Report	Completed		7/6/2011
VCP Receipt of Plan or Report	Completed		7/9/2011
VCP Status Request	Completed	8/19/2013	9/17/2013
VCP Receipt of Plan or Report	Completed		2/8/2016
VCP Opinion on Feasibility Study	Completed	2/24/2016	1/3/2018
VCP Receipt of Plan or Report	Completed		8/26/2016
VCP Receipt of Plan or Report	Completed		12/1/2017
VCP Status Request	Completed	9/24/2019	11/20/2019