

Cleanup Site Details

Cleanup Site ID: 824

Cleanup Site ID: 824	Facility/Site ID: 2130	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: Houghton Landfill King County Solid Waste Glossary						
Alternate Names: HOUGHTON LANDFILL, Houghton Landfill King County Solid Waste, Houghton Transfer Station, King Cnty Solid Waste Houghton						
LOCATION						
Address: 11724 NE 60TH ST		City: KIRKLAND	Zip Code: 98033	County: King		
Latitude: 47.66150	Longitude: -122.18275	WRIA: 8	Legislative District: 48	Congressional District: 1	TRS:	
DETAIL						
Status: Awaiting Cleanup	NFA Received? No	Is PSI site? No				
Statute: MTCA	NFA Date: N/A	Current VCP? No		Past VCP? No		
Site Rank: 5 - Lowest Assessed Risk	NFA Reason: N/A	Brownfield? No				
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control?		No		
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Houghton Landfill	Upland	Awaiting Cleanup	NW	Northwest Region	No Process	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	S	C	S			
Benzene	S	C				
Conventional Contaminants, Organic					C	
Halogenated Organics	S	C	S			
Metals - Other	S	C	S			
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received	Completed			3/1/1988		
Site Hazard Assessment	Completed		4/13/2021	5/10/2022		
Hazardous Sites Listing	Completed			5/13/2022		