

Cleanup Site Details

Cleanup Site ID: 8325

Cleanup Site ID: 8325 Facility/Site ID: 22543296 UST ID: 11131 Site Page Site Documents View Map

Cleanup Site Name: Husky Service Station Glossary

Alternate Names: Husky Service Station, LLOYD M BUTLER

LOCATION

Address: 200 E 2ND City: LIND Zip Code: 99341 County: Adams

Latitude: 46.97165 Longitude: -118.61363 WRIA: 41 Legislative District: 9 Congressional District: 4 TRS: 17N 33E 12

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Husky Service Station
 Upland
 Cleanup Started
 EA
 Eastern Region
 Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

 MEDIA

 Contaminant
 Soil
 Groundwater
 Surface Water
 Sediment
 Air
 Bedrock

 Petroleum-Other
 C

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

ActivityStatusStart DateEnd Date/Completion DateLUST - NotificationCompleted2/7/1995LUST - Report ReceivedCompleted3/23/1995