

Cleanup Site Details

Cleanup Site ID: 8325

Cleanup Site ID: 8325 **Facility/Site ID:** 22543296 **UST ID:** 11131 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Husky Service Station [Glossary](#)
Alternate Names: Husky Service Station, LLOYD M BUTLER

LOCATION

Address: 200 E 2ND **City:** LIND **Zip Code:** 99341 **County:** Adams
Latitude: 46.97165 **Longitude:** -118.61363 **WRIA:** 41 **Legislative District:** 9 **Congressional District:** 4 **TRS:** 17N 33E 12

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Eastern Region **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Husky Service Station	Upland	Cleanup Started	EA	Eastern Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/7/1995
LUST - Report Received	Completed		3/23/1995