

Cleanup Site Details

Cleanup Site ID: 8476

Cleanup Site ID: 8476 Facility/Site ID: 25561551 UST ID: 7450 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Petrocard S Kent [Glossary](#)

Alternate Names: PETROCARD, Petrocard Kent, Petrocard S Kent, PETROCARD SYSTEMS INC UST 7450, PETROCARD, INC., RUSSELL E THORP, Southcenter Oil, Superior Tire & Service Kent

LOCATION

Address: 828 CENTRAL AVE S **City:** KENT **Zip Code:** 98032 **County:** King
Latitude: 47.37341 **Longitude:** -122.22977 **WRIA:** 9 **Legislative District:** 33 **Congressional District:** 9 **TRS:** 22N 4E 24

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: PLIA **Responsible Unit:** Pollution Liability Ins Agcy **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Petrocard S Kent	Upland	Cleanup Started	PLIA	PLIA	PLIA Petroleum Technical

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		9/26/1991
LUST - Report Received	Completed		11/21/1991
LUST - Report Received	Completed		7/31/1998
LUST - Report Received	Completed		7/31/1998
LUST - Report Received	Completed		9/10/1998
LUST - Report Received	Completed		9/10/1998
LUST - Report Received	Completed		3/2/1999
LUST - Report Received	Completed		4/27/1999

Cleanup Site Details

Cleanup Site ID: 8476

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		11/30/1999
LUST - Report Received	Completed		2/17/2000
LUST - Report Received	Completed		5/30/2000
LUST - Report Received	Completed		8/21/2000
LUST - Report Received	Completed		11/27/2000
LUST - Report Received	Completed		4/25/2001
LUST - Report Received	Completed		12/18/2001
LUST - Report Received	Completed		9/30/2002
LUST - Report Received	Completed		12/11/2003
LUST - Report Received	Completed		6/8/2005
LUST - Report Received	Completed		10/27/2009
LUST - Report Received	Completed		12/17/2015
LUST - Report Received	Completed		12/17/2015
LUST - Report Received	Completed		12/17/2015
Early Notice Letter(s)	Completed		1/12/2016
VCP Opinion on Property Cleanup	Canceled	1/12/2016	1/1/1900