

Cleanup Site Details

Cleanup Site ID: 8578

Cleanup Site ID: 8578 Facility/Site ID: 28336331 UST ID: 9706 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: USCG Port Angeles Areas A & B [Glossary](#)

Alternate Names: US CG AIR STATION PORT ANGELES, USCG AIR STATION PORT ANGELES, USCG Port Angeles Areas A & B

LOCATION

Address: LAT 48 08 24 N LONG 123 24 30 W City: PORT ANGELES Zip Code: 98362 County: Clallam
Latitude: 48.13981 Longitude: -123.40963 WRIA: 18 Legislative District: 24 Congressional District: 6 TRS: 31N 6W 35

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Malte, Dean Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------------------|-----------|-----------------|-----------|--------------|--------------------|
| USCG PORT ANGELES-AREAS A & B | Upland | Cleanup Started | SW | Malte, Dean | Independent Action |
| USCG PORT ANGELES | Upland | Cleanup Started | SW | Malte, Dean | Independent Action |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|--|-------------------|---------------------------|------|------------------|------------------|------------|
| There are no current Institutional Controls in effect for this site. | | | | | | |

AFFECTED MEDIA & CONTAMINANTS

| Contaminant | MEDIA | | | | | |
|--------------------------------|-------|-------------|---------------|----------|-----|---------|
| | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Benzene | C | C | | | | |
| Other Non-Halogenated Organics | S | S | | | | |
| Petroleum-Diesel | RA | S | | | | |
| Petroleum-Gasoline | RB | S | | | | |
| Petroleum-Other | C | C | | | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|---------------------------|
| LUST - Notification | Completed | | 5/26/1995 |
| Site Discovery/Release Report Received | Completed | | 5/26/1995 |
| LUST - Report Received | Completed | | 6/12/1995 |
| LUST - Notification | Completed | | 5/1/1996 |

Cleanup Site Details

Cleanup Site ID: 8578

| SITE ACTIVITIES | | | |
|--|---------------|-------------------|--------------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Site Discovery/Release Report Received | Completed | | 5/1/1996 |
| LUST - Report Received | Completed | | 3/23/1998 |
| LUST - Report Received | Completed | | 4/16/1998 |
| LUST - Report Received | Completed | | 6/25/1998 |
| LUST - Report Received | Completed | | 10/2/1998 |
| LUST - Report Received | Completed | | 4/12/1999 |
| LUST - Report Received | Completed | | 1/29/2002 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 12/12/2011 |