

## Cleanup Site Details

Cleanup Site ID: 8651 Facility/Site ID: 30774595 UST ID: 4806 Site Page Site Documents View Map

Cleanup Site ID: 8651

Cleanup Site Name: Cowman Campbell Paints

Alternate Names: C and C Paints, Cowman Campbell Paint Co, COWMAN CAMPBELL PAINT COMPANY, Cowman Campbell Paints, HALCO

PROPERTIES LLC

LOCATION

Address: 5221 BALLARD AVE NW City: SEATTLE Zip Code: 98107 County: King

Latitude: 47.66557 Longitude: -122.38258 WRIA: 8 Legislative District: 36 Congressional District: 7 TRS: 25N 3E 11

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Cowman Campbell Paints	Upland	Cleanup Started	NW	Northwest Region	Independent Action

#### **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

#### **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
LUST - Other Hazardous Substance	С	С					
Non-Halogenated Solvents	С	С					
Petroleum-Diesel	С	С					
Petroleum-Gasoline	С	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA S - Suspected R - Remediated RB

RA - Remediated-Above RB - Remediated-Below

### SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/6/1990
LUST - Report Received	Completed		2/19/1991
LUST - Report Received	Completed		11/30/1992
LUST - Report Received	Completed		12/13/1995
LUST - Report Received	Completed		2/14/1996
LUST - Report Received	Completed		5/21/1996

Toxics Cleanup Program Report Generated: 5/3/2025 Page 1 of 2



VCP Receipt of Plan or Report

LUST - Report Received

LUST - Report Received

VCP Status Request

# Cleanup Site Details

ECOLOGY State of Washington Cleanup	o Site Details	Cleanup Site ID: 8651			
SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
LUST - Report Received	Completed		7/29/1996		
LUST - Report Received	Completed		10/16/1996		
LUST - Report Received	Completed		1/22/1997		
LUST - Report Received	Completed		4/29/1997		
LUST - Report Received	Completed		3/24/2000		
LUST - Notification	Completed		10/17/2000		
LUST - Report Received	Completed		11/28/2000		
LUST - Report Received	Completed		12/18/2000		
LUST - Report Received	Completed		1/2/2001		
LUST - Report Received	Completed		10/3/2002		
LUST - Report Received	Completed		10/3/2002		
LUST - Report Received	Completed		12/2/2003		
VCP Opinion on Property Cleanup	Completed	9/19/2011	11/29/2011		
VCP Opinion on Site Cleanup	Completed	9/19/2011	12/19/2011		
VCP Receipt of Plan or Report	Completed		9/7/2012		
VCP Opinion on Site Cleanup	Completed	11/9/2012	2/12/2012		
LUST - Report Received	Completed		7/25/2013		
VCP Opinion on Feasibility Study	Completed	7/25/2013	4/10/2014		
LUST - Report Received	Completed		10/22/2015		
LUST - Report Received	Completed		10/22/2015		
Early Notice Letter(s)	Completed		1/29/2016		
VCP Opinion on Remedial Investigation	Completed	1/29/2016	9/29/2017		
VCP Receipt of Plan or Report	Completed		7/12/2017		
VCP Receipt of Plan or Report	Completed		7/14/2017		

Completed

Completed

Completed

Completed

8/20/2019

10/13/2017

5/3/2018

8/16/2021

7/22/2021