

Cleanup Site Details

Cleanup Site ID: 8780

Cleanup Site ID: 8780 Facility/Site ID: 33911356 UST ID: 100973 Site Page Site Documents View Map

Cleanup Site Name: Yarrow Bay Marina Glossary

Alternate Names: YARROW BAY MARINA, YARROW BAY MARINA SEDIMENTS, Yarrow Bay Yacht Sales & Svc

LOCATION

Address: 5207 LAKE WASHINGTON BLVD NE City: KIRKLAND Zip Code: 98033 County: King

Latitude: 47.65516 Longitude: -122.20657 WRIA: 8 Legislative District: 48 Congressional District: 1 TRS:

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 1/24/2017 Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Myers, Dale R Responsible Unit: Northwest Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
YARROW BAY MARINA SEDIMENTS	Upland	No Further Action Required	NW	Myers, Dale R	Standard Voluntary Cleanup
Yarrow Bay Marina	Upland	No Further Action Required	NW	Myers, Dale R	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Restrict All Ground Water Extraction/Well Installation, Restrict Domestic Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Prevent the Reuse or Relocation of Site Soil, Ongoing Maintenance of Remedy, Control Stormwater, Control Vapor/Gas, Maintain/Protect Monitoring System	12/21/2016	2016122100003	King	172505-9130

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Lead		RB				
Non-Halogenated Solvents	RB					
Other Non-Halogenated Organics	RB	RB				
Petroleum-Diesel	RB	RB				
Petroleum-Gasoline	RB	RB				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		3/27/1992

Toxics Cleanup Program Report Generated: 10/20/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Site Discovery/Release Report Received	Completed		3/27/1992			
LUST - Report Received	Completed		6/19/1992			
Site Status Changed to NFA	Completed		1/1/1994			
Independent Report Review - Paid	Completed		1/4/1994			
LUST - Report Received	Completed		3/21/1994			
Site Discovery/Release Report Received	Completed		3/30/1994			
Initial Investigation / Federal Preliminary Assessment	Completed		6/1/1994			
VCP Opinion on Interim Action	Completed	6/7/2007	7/25/2007			
VCP Opinion on Cleanup Action Plan	Completed	1/9/2008	1/30/2008			
LUST - Site Characterization Report	Completed		4/29/2008			
Reopen Site	Completed		7/24/2008			
VCP Status Request	Completed	12/30/2009	1/25/2010			
VCP Opinion on Cleanup Action	Completed	1/12/2010	3/24/2010			
VCP Opinion on Cleanup Action	Completed	3/24/2010	4/15/2010			
Site Hazard Assessment	Canceled		5/3/2013			
VCP Status Request	Completed	7/21/2014	8/21/2014			
VCP Receipt of Plan or Report	Completed		10/22/2014			
LUST - Report Received	Completed		6/3/2016			
VCP Receipt of Plan or Report	Completed		6/3/2016			
VCP Opinion on Feasibility Study	Completed	6/3/2016	1/24/2017			
Site Status Changed to NFA	Completed		1/24/2017			
LUST - Report Received	Completed		1/16/2018			
LUST - Report Received	Completed		11/15/2022			
VCP Receipt of Plan or Report	Completed		11/13/2023			
Periodic Review	Planned	12/21/2023	1/1/1900			