

Cleanup Site Details

Cleanup Site ID: 8836

Cleanup Site ID: 8836
Facility/Site ID: 35363194
UST ID: 5060
[Site Page](#)
[Site Documents](#)
[View Map](#)
Cleanup Site Name: Chevron 90619
[Glossary](#)
Alternate Names: CHEVRON 90619, Chevron USA Inc SS 90619

LOCATION

Address: 1205 WASHINGTON ST
City: BELLINGHAM
Zip Code: 98225
County: Whatcom
Latitude: 48.76042
Longitude: -122.48815
WRIA: 1
Legislative District: 42
Congressional District: 2
TRS: 38N 2E 25

DETAIL

Status: No Further Action
NFA Received? Yes
Is PSI site? Yes
Statute: MTCA
NFA Date: 1/7/2021
Current VCP? No
Past VCP? No
Site Rank: 4 - Low-Moderate Risk
NFA Reason: Ecology Supervised/Conducted Cleanup
Brownfield? No
Site Manager: Guenther, John
Responsible Unit: Northwest
Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 90619	Upland	No Further Action Required	NW	Guenther, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Report Received	Completed		1/23/1991
LUST - Notification	Completed		1/25/1991
LUST - Report Received	Completed		3/11/1991
LUST - Report Received	Completed		5/21/1991
LUST - Report Received	Completed		8/26/1991
LUST - Report Received	Completed		10/11/1991
LUST - Report Received	Completed		2/27/1992
LUST - Report Received	Completed		3/23/1992
LUST - Report Received	Completed		9/22/1992

Cleanup Site Details

Cleanup Site ID: 8836

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		2/10/1993
LUST - Report Received	Completed		1/21/1994
LUST - Report Received	Completed		4/22/1994
LUST - Report Received	Completed		8/3/1994
LUST - Report Received	Completed		11/14/1994
LUST - Report Received	Completed		1/10/1995
LUST - Report Received	Completed		8/16/1995
LUST - Report Received	Completed		10/26/1995
LUST - Report Received	Completed		4/3/1996
Early Notice Letter(s)	Completed		8/6/2015
Site Hazard Assessment/Federal Site Inspection	Completed	5/8/2017	12/26/2017
Order/Decree/Amendment	Completed	8/23/2017	1/7/2021
Hazardous Sites Listing/NPL	Completed		2/7/2018
Remove site from Hazardous Sites List	Completed		1/4/2021
Site Status Changed to NFA	Completed		1/7/2021