

# Cleanup Site Details

Cleanup Site ID: 8836

**Cleanup Site ID:** 8836     
**Facility/Site ID:** 35363194     
**UST ID:** 5060     
[Site Page](#)   
[Site Documents](#)   
[View Map](#)  
**Cleanup Site Name:** Chevron 90619     
[Glossary](#)  
**Alternate Names:** CHEVRON 90619, Chevron USA Inc SS 90619

## LOCATION

**Address:** 1205 WASHINGTON ST     
**City:** BELLINGHAM     
**Zip Code:** 98225     
**County:** Whatcom  
**Latitude:** 48.76042   
**Longitude:** -122.48815   
**WRIA:** 1     
**Legislative District:** 42     
**Congressional District:** 2     
**TRS:** 38N 2E 25

## DETAIL

**Status:** No Further Action     
**NFA Received?** Yes     
**Is PSI site?** Yes  
**Statute:** MTCA     
**NFA Date:** 1/7/2021     
**Current VCP?** No   
**Past VCP?** No  
**Site Rank:** 4 - Low-Moderate Risk     
**NFA Reason:** Ecology Supervised/Conducted Cleanup     
**Brownfield?** No  
**Site Manager:** Guenther, John     
**Responsible Unit:** Northwest     
**Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 90619	Upland	No Further Action Required	NW	Guenther, John	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				

**Key:**  
B - Below Cleanup Level     
C - Confirmed Above Cleanup Level     
RA - Remediated-Above  
S - Suspected     
R - Remediated     
RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Report Received	Completed		1/23/1991
LUST - Notification	Completed		1/25/1991
LUST - Report Received	Completed		3/11/1991
LUST - Report Received	Completed		5/21/1991
LUST - Report Received	Completed		8/26/1991
LUST - Report Received	Completed		10/11/1991
LUST - Report Received	Completed		2/27/1992
LUST - Report Received	Completed		3/23/1992
LUST - Report Received	Completed		9/22/1992

# Cleanup Site Details

Cleanup Site ID: 8836

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		2/10/1993
LUST - Report Received	Completed		1/21/1994
LUST - Report Received	Completed		4/22/1994
LUST - Report Received	Completed		8/3/1994
LUST - Report Received	Completed		11/14/1994
LUST - Report Received	Completed		1/10/1995
LUST - Report Received	Completed		8/16/1995
LUST - Report Received	Completed		10/26/1995
LUST - Report Received	Completed		4/3/1996
Early Notice Letter(s)	Completed		8/6/2015
Site Hazard Assessment/Federal Site Inspection	Completed	5/8/2017	12/26/2017
Order/Decree/Amendment	Completed	8/23/2017	1/7/2021
Hazardous Sites Listing/NPL	Completed		2/7/2018
Remove site from Hazardous Sites List	Completed		1/4/2021
Site Status Changed to NFA	Completed		1/7/2021