

# Cleanup Site Details

Cleanup Site ID: 8836

<b>Cleanup Site ID:</b> 8836	<b>Facility/Site ID:</b> 35363194	<b>UST ID:</b> 5060	<a href="#">Site Page</a>	<a href="#">Site Documents</a>	<a href="#">View Map</a>
<b>Cleanup Site Name:</b> Chevron 90619					<a href="#">Glossary</a>
<b>Alternate Names:</b> CHEVRON 90619, Chevron USA Inc SS 90619					
<b>LOCATION</b>					
<b>Address:</b> 1205 WASHINGTON ST		<b>City:</b> BELLINGHAM	<b>Zip Code:</b> 98225	<b>County:</b> Whatcom	
<b>Latitude:</b> 48.76042	<b>Longitude:</b> -122.48815	<b>WRIA:</b> 1	<b>Legislative District:</b> 42	<b>Congressional District:</b> 2	<b>TRS:</b> 38N 2E 25
<b>DETAIL</b>					
<b>Status:</b> No Further Action	<b>NFA Received?</b> Yes	<b>Is PSI site?</b> Yes			
<b>Statute:</b> MTCA	<b>NFA Date:</b> 1/7/2021	<b>Current VCP?</b> No	<b>Past VCP?</b> No		
<b>Site Rank:</b> 4 - Low-Moderate Risk	<b>NFA Reason:</b> Ecology Supervised/Conducted Cleanup	<b>Brownfield?</b> No			
<b>Site Manager:</b> Guenther, John	<b>Responsible Unit:</b> Northwest	<b>Active Institutional Control?</b> No			
<b>CLEANUP UNITS</b>					
<b>Cleanup Unit Name</b>	<b>Unit Type</b>	<b>Unit Status</b>	<b>Resp Unit</b>	<b>Unit Manager</b>	<b>Current Process</b>
Chevron 90619	Upland	No Further Action Required	NW	Guenther, John	Ecology-supervised or conducted
<b>ACTIVE INSTITUTIONAL CONTROLS</b>					
<b>Instrument Type</b>	<b>Restriction Media</b>	<b>Restrictions/Requirements</b>	<b>Date</b>	<b>Recording Number</b>	<b>Recording County</b>
There are no current Institutional Controls in effect for this site.					
<b>AFFECTED MEDIA &amp; CONTAMINANTS</b>					
<b>MEDIA</b>					
<b>Contaminant</b>	<b>Soil</b>	<b>Groundwater</b>	<b>Surface Water</b>	<b>Sediment</b>	<b>Air</b>
Benzene	RB	RB			
<b>Key:</b> B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above S - Suspected                      R - Remediated                      RB - Remediated-Below					
<b>SITE ACTIVITIES</b>					
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>		
LUST - Report Received	Completed		1/23/1991		
LUST - Notification	Completed		1/25/1991		
LUST - Report Received	Completed		3/11/1991		
LUST - Report Received	Completed		5/21/1991		
LUST - Report Received	Completed		8/26/1991		
LUST - Report Received	Completed		10/11/1991		
LUST - Report Received	Completed		2/27/1992		
LUST - Report Received	Completed		3/23/1992		
LUST - Report Received	Completed		9/22/1992		
<b>Toxics Cleanup Program</b> <span style="float: right;"><b>Report Generated: 7/1/2025</b></span> <span style="float: right;"><b>Page 1 of 2</b></span>					

# Cleanup Site Details

Cleanup Site ID: 8836

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		2/10/1993
LUST - Report Received	Completed		1/21/1994
LUST - Report Received	Completed		4/22/1994
LUST - Report Received	Completed		8/3/1994
LUST - Report Received	Completed		11/14/1994
LUST - Report Received	Completed		1/10/1995
LUST - Report Received	Completed		8/16/1995
LUST - Report Received	Completed		10/26/1995
LUST - Report Received	Completed		4/3/1996
Early Notice Letter(s)	Completed		8/6/2015
Site Hazard Assessment	Completed	5/8/2017	12/26/2017
Order/Decree/Amendment	Completed	8/23/2017	1/7/2021
Hazardous Sites Listing	Completed		2/7/2018
Remove site from Hazardous Sites List	Completed		1/4/2021
Site Status Changed to NFA	Completed		1/7/2021