

Cleanup Site Details

Cleanup Site ID: 8836

Cleanup Site ID: 8836	Facility/Site ID: 35363194	UST ID: 5060	Site Page	Site Documents	View Map
Cleanup Site Name: Chevron 90619 Glossary					
Alternate Names: CHEVRON 90619, Chevron USA Inc SS 90619					
LOCATION					
Address: 1205 WASHINGTON ST		City: BELLINGHAM	Zip Code: 98225	County: Whatcom	
Latitude: 48.76042	Longitude: -122.48815	WRIA: 1	Legislative District: 42	Congressional District: 2	TRS: 38N 2E 25
DETAIL					
Status: No Further Action	NFA Received? Yes	Is PSI site? Yes			
Statute: MTCA	NFA Date: 1/7/2021	Current VCP? No		Past VCP? No	
Site Rank: 4 - Low-Moderate Risk	NFA Reason: Ecology Supervised/Conducted Cleanup	Brownfield? No			
Site Manager: Guenther, John	Responsible Unit: Northwest	Active Institutional Control? No			
CLEANUP UNITS					
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 90619	Upland	No Further Action Required	NW	Guenther, John	Ecology-supervised or conducted
ACTIVE INSTITUTIONAL CONTROLS					
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County
There are no current Institutional Controls in effect for this site.					
AFFECTED MEDIA & CONTAMINANTS					
MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air
Benzene	RB	RB			
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below					
SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
LUST - Report Received	Completed		1/23/1991		
LUST - Notification	Completed		1/25/1991		
LUST - Report Received	Completed		3/11/1991		
LUST - Report Received	Completed		5/21/1991		
LUST - Report Received	Completed		8/26/1991		
LUST - Report Received	Completed		10/11/1991		
LUST - Report Received	Completed		2/27/1992		
LUST - Report Received	Completed		3/23/1992		
LUST - Report Received	Completed		9/22/1992		
Toxics Cleanup Program Report Generated: 10/14/2025 Page 1 of 2					

Cleanup Site Details

Cleanup Site ID: 8836

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		2/10/1993
LUST - Report Received	Completed		1/21/1994
LUST - Report Received	Completed		4/22/1994
LUST - Report Received	Completed		8/3/1994
LUST - Report Received	Completed		11/14/1994
LUST - Report Received	Completed		1/10/1995
LUST - Report Received	Completed		8/16/1995
LUST - Report Received	Completed		10/26/1995
LUST - Report Received	Completed		4/3/1996
Early Notice Letter(s)	Completed		8/6/2015
Site Hazard Assessment	Completed	5/8/2017	12/26/2017
Order/Decree/Amendment	Completed	8/23/2017	1/7/2021
Hazardous Sites Listing	Completed		2/7/2018
Remove site from Hazardous Sites List	Completed		1/4/2021
Site Status Changed to NFA	Completed		1/7/2021