

# Cleanup Site Details

Cleanup Site ID: 8879

Cleanup Site ID: 8879      Facility/Site ID: 36296841      UST ID: 97430      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Cascade Autovon Co      [Glossary](#)

Alternate Names: CASCADE AUTOVON, Cascade Autovon Co, CASCADE AUTOVON COMPANY

## LOCATION

Address: 12727 412TH AVE SE      City: NORTH BEND      Zip Code: 98045      County: King  
Latitude: 47.48527      Longitude: -121.79173      WRIA: 7      Legislative District: 5      Congressional District: 8      TRS: 23N 8E 9

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 8/9/2018      Current VCP? No      Past VCP? Yes  
Site Rank: 3 - Moderate Risk      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
Site Manager: Song, Jing      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Cascade Autovon Co	Upland	No Further Action Required	NW	Song, Jing	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB	B				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		6/20/1991
Site Discovery/Release Report Received	Completed		6/20/1991
LUST - Report Received	Completed		11/27/1991
LUST - Report Received	Completed		4/16/1992
LUST - Report Received	Completed		6/25/1992
LUST - Report Received	Completed		9/29/1992
LUST - Report Received	Completed		1/25/1993
LUST - Report Received	Completed		3/14/1994
LUST - Report Received	Completed		5/10/1995
Initial Investigation / Federal Preliminary Assessment	Completed		4/20/2011

# Cleanup Site Details

Cleanup Site ID: 8879

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Site Hazard Assessment/Federal Site Inspection	Completed	5/7/2013	6/28/2013
Hazardous Sites Listing/NPL	Completed		8/8/2013
LUST - Report Received	Completed		10/27/2016
VCP Opinion on Remedial Investigation	Completed	10/27/2016	8/31/2017
LUST - Report Received	Completed		9/7/2017
LUST - Report Received	Completed		2/6/2018
VCP Opinion on Site Cleanup	Completed	2/6/2018	8/9/2018
Remove site from Hazardous Sites List	Completed		8/9/2018
Site Status Changed to NFA	Completed		8/9/2018
Petroleum Impacts to Groundwater Model Remedies	Completed		8/9/2018