

Cleanup Site Details

Cleanup Site ID: 8879

Cleanup Site ID: 8879 Facility/Site ID: 36296841 UST ID: 97430 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Cascade Autovon Co [Glossary](#)

Alternate Names: CASCADE AUTOVON, Cascade Autovon Co, CASCADE AUTOVON COMPANY

LOCATION

Address: 12727 412TH AVE SE City: NORTH BEND Zip Code: 98045 County: King
Latitude: 47.48527 Longitude: -121.79173 WRIA: 7 Legislative District: 5 Congressional District: 8 TRS: 23N 8E 9

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 8/9/2018 Current VCP? No Past VCP? Yes
Site Rank: 3 - Moderate Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Song, Jing Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Cascade Autovon Co	Upland	No Further Action Required	NW	Song, Jing	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB	B				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		6/20/1991
Site Discovery/Release Report Received	Completed		6/20/1991
LUST - Report Received	Completed		11/27/1991
LUST - Report Received	Completed		4/16/1992
LUST - Report Received	Completed		6/25/1992
LUST - Report Received	Completed		9/29/1992
LUST - Report Received	Completed		1/25/1993
LUST - Report Received	Completed		3/14/1994
LUST - Report Received	Completed		5/10/1995
Initial Investigation / Federal Preliminary Assessment	Completed		4/20/2011

Cleanup Site Details

Cleanup Site ID: 8879

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment	Completed	5/7/2013	6/28/2013
Hazardous Sites Listing	Completed		8/8/2013
LUST - Report Received	Completed		10/27/2016
VCP Opinion on Remedial Investigation	Completed	10/27/2016	8/31/2017
LUST - Report Received	Completed		9/7/2017
LUST - Report Received	Completed		2/6/2018
VCP Opinion on Site Cleanup	Completed	2/6/2018	8/9/2018
Remove site from Hazardous Sites List	Completed		8/9/2018
Site Status Changed to NFA	Completed		8/9/2018
Petroleum Impacts to Groundwater Model Remedies	Completed		8/9/2018