

# Cleanup Site Details

Cleanup Site ID: 9107

<b>Cleanup Site ID:</b> 9107	<b>Facility/Site ID:</b> 41995646	<b>UST ID:</b> 101134	<a href="#">Site Page</a>	<a href="#">Site Documents</a>	<a href="#">View Map</a>	
<b>Cleanup Site Name:</b> ARCO 05300 AMHAZ INC <a href="#">Glossary</a>						
<b>Alternate Names:</b> ARCO 05300, ARCO 05300 AMHAZ INC, Arco 5300, ARCO 5300 PSI 5570, ARCO FACILITY 05300 AMHAZ INC, ARCO FACILITY 05300 KACY PROPERTIES LLC						
<b>LOCATION</b>						
<b>Address:</b> 710 15TH AVE		<b>City:</b> LONGVIEW	<b>Zip Code:</b> 98632	<b>County:</b> Cowlitz		
<b>Latitude:</b> 46.12675	<b>Longitude:</b> -122.94084	<b>WRIA:</b> 25	<b>Legislative District:</b> 19	<b>Congressional District:</b> 3	<b>TRS:</b> 7N 2W 4	
<b>DETAIL</b>						
<b>Status:</b> No Further Action	<b>NFA Received?</b> Yes	<b>Is PSI site?</b> No				
<b>Statute:</b> MTCA	<b>NFA Date:</b> 11/7/2023	<b>Current VCP?</b> No		<b>Past VCP?</b> No		
<b>Site Rank:</b> N/A	<b>NFA Reason:</b> Petroleum Technical Assistance Program (PTAP) by PLIA	<b>Brownfield?</b> No				
<b>Site Manager:</b> PLIA	<b>Responsible Unit:</b> Pollution Liability Ins Agcy	<b>Active Institutional Control?</b> No				
<b>CLEANUP UNITS</b>						
<b>Cleanup Unit Name</b>	<b>Unit Type</b>	<b>Unit Status</b>	<b>Resp Unit</b>	<b>Unit Manager</b>	<b>Current Process</b>	
ARCO 05300 AMHAZ INC	Upland	No Further Action Required	PLIA	PLIA	PLIA Petroleum Technical	
<b>ACTIVE INSTITUTIONAL CONTROLS</b>						
<b>Instrument Type</b>	<b>Restriction Media</b>	<b>Restrictions/Requirements</b>	<b>Date</b>	<b>Recording Number</b>	<b>Recording County</b>	<b>Tax Parcel</b>
There are no current Institutional Controls in effect for this site.						
<b>AFFECTED MEDIA &amp; CONTAMINANTS</b>						
<b>MEDIA</b>						
<b>Contaminant</b>	<b>Soil</b>	<b>Groundwater</b>	<b>Surface Water</b>	<b>Sediment</b>	<b>Air</b>	<b>Bedrock</b>
Benzene	RB	RB			B	
Lead	B	RB				
Methyl tertiary-butyl ether	RB	RB			B	
Non-Halogenated Solvents	RB	B			B	
Petroleum-Gasoline	RB	RB			B	
<b>Key:</b> B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above S - Suspected                      R - Remediated                      RB - Remediated-Below						
<b>SITE ACTIVITIES</b>						
<b>Activity</b>	<b>Status</b>		<b>Start Date</b>	<b>End Date/ Completion Date</b>		
LUST - Notification	Completed			12/18/2009		
Site Discovery/Release Report Received	Completed			12/18/2009		
LUST - Report Received	Completed			5/5/2010		
Initial Investigation / Federal Preliminary Assessment	Completed			9/30/2011		
Early Notice Letter(s)	Completed			9/30/2011		
<b>Toxics Cleanup Program</b>						

# Cleanup Site Details

Cleanup Site ID: 9107

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		8/12/2013
LUST - Report Received	Completed		9/17/2013
LUST - Report Received	Completed		9/17/2013
LUST - Report Received	Completed		10/4/2013
LUST - Report Received	Completed		2/10/2014
LUST - Report Received	Completed		2/10/2014
LUST - Report Received	Completed		4/1/2014
LUST - Report Received	Completed		10/1/2014
LUST - Report Received	Completed		2/6/2015
LUST - Report Received	Completed		2/5/2016
LUST - Report Received	Completed		3/2/2016
LUST - Report Received	Completed		5/23/2017
LUST - Report Received	Completed		6/12/2017
LUST - Report Received	Completed		3/1/2018
LUST - Report Received	Completed		10/31/2018
LUST - Report Received	Completed		3/19/2019
LUST - Report Received	Completed		9/16/2019
LUST - Report Received	Completed		1/21/2020
LUST - Report Received	Completed		8/18/2020
LUST - Report Received	Completed		2/12/2021
Petroleum Impacts to Groundwater Model Remedies	Completed		11/7/2023
Site Status Changed to NFA	Completed		11/7/2023