

Cleanup Site Details

Cleanup Site ID: 9152

Cleanup Site ID: 9152 Facility/Site ID: 42978181 UST ID: 8263 Site Page Site Documents View Map

Cleanup Site Name: Port of Longview TPH

Alternate Names: LONGVIEW PORT, LONGVIEW PORT OF, Port of Longview, Port of Longview TPH, Port of Longview, Berths 1 & 2

LOCATION

Address: 10 PORT WAY City: LONGVIEW Zip Code: 98632 County: Cowlitz

Latitude: 46.10845 Longitude: -122.95723 WRIA: 25 Legislative District: 19 Congressional District: 3 TRS: 7N 2W 8

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Meng, Sam Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Port of Longview	Upland	Cleanup Started	SW	Morris, Matt	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

	Instrument Type	Restriction	Restrictions/Requirements	Date	Recording	Recording	Tax Parcel
1	moti dimoni i ypo	Media	resource and resource and resource	Date	Number	County	

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

		MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Petroleum-Diesel	С	С					
Petroleum-Gasoline	С	С					
Petroleum-Other	С	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/20/1991
LUST - Report Received	Completed		6/26/1991
LUST - Notification	Completed		10/15/1992
Site Discovery/Release Report Received	Completed		10/15/1992
LUST - Report Received	Completed		7/9/1993
LUST - Report Received	Completed		9/2/1993
LUST - Report Received	Completed		12/7/1994
LUST - Report Received	Completed		12/9/1994

Toxics Cleanup Program Report Generated: 4/28/2024 Page 1 of 2



Remedial Investigation and/or Feasibility Study

Cleanup Site Details

State of Washington Cleanup	Site Details	Clea	nup Site ID: 9152				
SITE ACTIVITIES							
Activity	Status	Start Date	End Date/ Completion Date				
Initial Investigation / Federal Preliminary Assessment	Completed		9/30/2011				
Early Notice Letter(s)	Completed		9/30/2011				
Site Hazard Assessment/Federal Site Inspection	Completed	9/16/2013	1/15/2014				
Site Hazard Assessment/Federal Site Inspection	Completed	1/15/2014	10/22/2014				
Hazardous Sites Listing/NPL	Completed		10/22/2014				
Interim Action - Plan	Completed	9/25/2017	2/13/2019				
Order/Decree/Amendment	In Process	1/16/2018					
Remedial Investigation and/or FS Work Plan	Completed	2/13/2019	10/25/2019				
Interim Action - Construction	Completed	4/12/2019	5/31/2019				
Remedial Investigation and/or Feasibility Study	In Process	10/25/2019					

In Process

10/25/2019