| DEPARTMENT OF ECOLOGY State of Washington | | | | | | | | | Cleanup Site ID: 9217 | | |
|---|-----------------------|------------------------|--------------------------|---|---|-----------------|-------------------------|-------------------------|-----------------------|--|--|
| Cleanup Site ID: 9217 Facility/Site ID: 6919 | | | UST ID: 437159 Site Page | | | | Site Documents View Map | | | | |
| Cleanup Site Name: King County Shops Glossary | | | | | | | | | | | |
| Alternate Names: King County Shops, King County Shops Site, SUNSET MATERIALS INC RENTON | | | | | | | | | | | |
| LOCATION | | | | | | | | | | | |
| Address: 18825 SE RENTON MAPLE VALLEY RD City: RENTON Zip Code: 98058 County: King | | | | | | | | | | | |
| Latitude: 47.46090 Longitude: -122.09200 WRIA: 8 Legislative Dist | | | | | strict: 11 Congressional District: 8 TRS: 23N 6E 19 | | | | | | |
| DETAIL | | | | | | | | | | | |
| Status: Cleanup Started NFA Received? | | | No Is PSI s | | | | site? No | | | | |
| Statute: MTCA | itute: MTCA NFA Date: | | | N/A Currer | | | | nt VCP? No Past VCP? No | | | |
| Site Rank: N/A NFA Reason: N/A | | | | Brownfield? No | | | | | | | |
| Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No | | | | | | | | | | | |
| CLEANUP UNITS | | | | | | | . | | | | |
| Cleanup Unit Name | Unit Type | Unit Status | | Resp Unit | Unit Manager | | Current Process | | | | |
| King County Shops | Upland | Upland Cleanup Started | | NW | Northwest | orthwest Region | | Independent Action | | | |
| ACTIVE INSTITUTIONAL CONTROLS | | | | | | | | | | | |
| Instrument Type Restriction Media Restrictions/Requirements | | | | | Date Ro | g Recor Cou | | Tax Parcel | | | |
| There are no current Institutional Controls in effect for this site. | | | | | | | | | | | |
| | | | | | | | | | | | |
| AFFECTED MEDIA & CONTAMINANTS | | | | | | | | | | | |
| O su tombre de la companya de | | | 0 | MEDIA Groundwater Surface Water Sediment Air Bedrock | | | | | | | |
| Contaminant Arsenic | | Soil | C | water | ter Surface Water | | eaiment | Air | Bedrock | | |
| Benzene | | С | | | | | | | | | |
| Petroleum-Diesel | | C | | | | | | | | | |
| Petroleum-Other | | C | С | | | | | | | | |
| Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected R - Remediated RB - Remediated-Below | | | | | | | | | | | |
| SITE ACTIVITIES | | | | | | | | | | | |
| Activity | | | | | Status | St | art Date | | Ind Date/ | | |
| LUST - Notification | | | | C | Completed | | | 2/11/1998 | | | |
| LUST - Report Received | | | | C | Completed | | | 2/11/1998 | | | |
| Site Discovery/Release Report Received | | | | C | Completed | | | 2/11/1998 | | | |
| LUST - Report Received | | | | C | Completed | | | 9/1/2016 | | | |
| | | | | | | | | | | | |