

Cleanup Site Details

Cleanup Site ID: 9387

Cleanup Site ID: 9387 Facility/Site ID: 47812495 UST ID: 6606 Site Page Site Documents View Map

Cleanup Site Name: Guy Bennett Lumber Company Glossary

Alternate Names: GUY BENNETT LUMBER COMPANY, GUY BENNETT LUMBER COMPANY UST 6606

LOCATION

Address: 1785 Elm St City: Clarkston Zip Code: 99403 County: Asotin

Latitude: 46.41348 Longitude: -117.07900 WRIA: 35 Legislative District: 9 Congressional District: 5 TRS: 11N 46E 20

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Kercher, Beth Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Guy Bennett Lumber Company
 Upland
 Cleanup Started
 EA
 Kercher, Beth
 Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

 MEDIA

 Contaminant
 Soil
 Groundwater
 Surface Water
 Sediment
 Air
 Bedrock

 Petroleum-Other
 C
 Image: Contaminant of the petroleum of the petroleum

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		1/29/1999
LUST - Report Received	Completed		2/10/1999
Administrative Correspondence	Completed		6/5/2023
LUST Review Memo	Completed		6/5/2023
Property Access Agreement	Canceled	6/5/2023	2/8/2024

Toxics Cleanup Program Report Generated: 8/23/2025 Page 1 of 1