

# Cleanup Site Details

Cleanup Site ID: 9440

Cleanup Site ID: 9440      Facility/Site ID: 49354234      UST ID: 7372      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Whitten Oil 1      [Glossary](#)

Alternate Names: WHITTEN 1, Whitten Oil 1, WHITTYS CHEVRON, WHITTYS NORTHTOWN CHEVRON

## LOCATION

Address: 370 W 5TH      City: COLVILLE      Zip Code: 99114      County: Stevens  
Latitude: 48.54894      Longitude: -117.90972      WRIA: 59      Legislative District: 7      Congressional District: 5      TRS: 35N 39E 9

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? Yes  
Site Rank: 4 - Low-Moderate Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Uecker, Ted      Responsible Unit: Eastern      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Whitten Oil 1	Upland	Cleanup Started	EA	Uecker, Ted	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene		C			S	
Petroleum-Diesel		C			S	
Petroleum-Gasoline	C	C			S	
Petroleum-Other	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		8/10/1989
LUST - Report Received	Completed		3/26/1990
Site Hazard Assessment/Federal Site Inspection	Completed	3/4/2013	8/12/2013
Hazardous Sites Listing/NPL	Completed		8/21/2013
VCP Receipt of Plan or Report	Completed		6/19/2018
VCP Receipt of Plan or Report	Completed		6/19/2018
VCP Receipt of Plan or Report	Completed		6/19/2018

# Cleanup Site Details

Cleanup Site ID: 9440

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
VCP Receipt of Plan or Report	Completed		9/11/2018
VCP Receipt of Plan or Report	Completed		5/23/2019
VCP Receipt of Plan or Report	Completed		10/18/2019
VCP Receipt of Plan or Report	Completed		4/1/2020
VCP Receipt of Plan or Report	Completed		3/11/2021
VCP Receipt of Plan or Report	Completed		5/24/2021
VCP Receipt of Plan or Report	Completed		11/8/2021
VCP Technical Assistance	Completed		12/16/2021
VCP Receipt of Plan or Report	Completed		4/20/2022
VCP Technical Assistance	Completed		5/24/2022
VCP Receipt of Plan or Report	Completed		5/16/2023
VCP Receipt of Plan or Report	Completed		11/1/2023
VCP Opinion on Site Cleanup Plan	Completed	11/1/2023	11/20/2023
Order/Decree/Amendment	In Process	5/6/2024	
Remedial Investigation and/or FS Work Plan	In Process	10/31/2024	