

Cleanup Site Details

Cleanup Site ID: 9440

Cleanup Site ID: 9440 Facility/Site ID: 49354234 UST ID: 7372 <u>Site Page</u> <u>Site Documents</u> <u>View Map</u>

Cleanup Site Name: Whitten Oil 1

Alternate Names: WHITTEN 1, Whitten Oil 1, WHITTY'S CHEVRON, WHITTYS CHEVRON, WHITTYS NORTHTOWN CHEVRON

LOCATION

Address: 370 W 5TH City: COLVILLE Zip Code: 99114 County: Stevens

Latitude: 48.54894 Longitude: -117.90972 WRIA: 59 Legislative District: 7 Congressional District: 5 TRS: 35N 39E 9

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 4 - Low-Moderate Risk NFA Reason: N/A Brownfield? No

Site Manager: Uecker, Ted Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Whitten Oil 1
 Upland
 Cleanup Started
 EA
 Uecker, Ted
 Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene		С			S		
Petroleum-Diesel		С			S		
Petroleum-Gasoline	С	С			S		
Petroleum-Other	С	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		8/10/1989
LUST - Report Received	Completed		3/26/1990
Site Hazard Assessment/Federal Site Inspection	Completed	3/4/2013	8/12/2013
Hazardous Sites Listing/NPL	Completed		8/21/2013
VCP Receipt of Plan or Report	Completed		6/19/2018
VCP Receipt of Plan or Report	Completed		6/19/2018
VCP Receipt of Plan or Report	Completed		6/19/2018

Toxics Cleanup Program Report Generated: 5/10/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
VCP Receipt of Plan or Report	Completed		9/11/2018			
VCP Receipt of Plan or Report	Completed		5/23/2019			
VCP Receipt of Plan or Report	Completed		10/18/2019			
VCP Receipt of Plan or Report	Completed		4/1/2020			
VCP Receipt of Plan or Report	Completed		3/11/2021			
VCP Receipt of Plan or Report	Completed		5/24/2021			
VCP Receipt of Plan or Report	Completed		11/8/2021			
VCP Technical Assistance	Completed		12/16/2021			
VCP Receipt of Plan or Report	Completed		4/20/2022			
VCP Technical Assistance	Completed		5/24/2022			
VCP Receipt of Plan or Report	Completed		5/16/2023			
VCP Receipt of Plan or Report	Completed		11/1/2023			
VCP Opinion on Site Cleanup Plan	Completed	11/1/2023	11/20/2023			
Order/Decree/Amendment	In Process	5/6/2024				
Remedial Investigation and/or FS Work Plan	Completed	10/31/2024	1/29/2025			

Cleanup Site ID: 9440