

Cleanup Site Details

Cleanup Site ID: 9457

Cleanup Site ID: 9457	Facility/Site ID: 49626114	UST ID: 350	Site Page	Site Documents	View Map
Cleanup Site Name: Paine Field					Glossary
Alternate Names: Paine Field, PAINE FIELD AIRPORT, Paine Field Fire Training Pit PFAS, SCA FORMER FIRE PIT, SNOHOMISH CNTY AIRPORT, SNOHOMISH CNTY AIRPORT 100TH ST, SNOHOMISH COUNTY AIRPORT, Snohomish County Airport Fire Pit					

LOCATION

Address: 3220 100th St SW			City: Everett	Zip Code: 98204	County: Snohomish
Latitude: 47.90300	Longitude: -122.28970	WRIA: 8	Legislative District: 21	Congressional District: 2	TRS: 28N 4E 22

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: N/A	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
PAINE FIELD	Upland	Cleanup Started	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	C	C				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		10/30/1989
LUST - Report Received	Completed		4/25/1990
LUST - Notification	Completed		6/25/1990
LUST - Report Received	Completed		3/4/1991
LUST - Report Received	Completed		10/4/1994
LUST - Report Received	Completed		10/31/2000