

Cleanup Site Details

Cleanup Site ID: 95

Cleanup Site ID: 95	Facility/Site ID: 2098	UST ID: 10419	Site Page	Site Documents	View Map
Cleanup Site Name: Boeing Company Kent Benaroya					
Alternate Names: BOEING COMPANY KENT BENAROYA, BOEING KENT BENAROYA, Boeing Surplus, KENT BENAROYA					

[Glossary](#)

LOCATION

Address: 8118 S 208TH ST	City: KENT	Zip Code: 98032	County: King
Latitude: 47.41652	Longitude: -122.23136	WRIA: 9	Legislative District: 33
	Congressional District: 9	TRS:	

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: N/A	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Kent Benaroya	Upland	Cleanup Started	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	S	S				
Metals Priority Pollutants	S	S				
Non-Halogenated Solvents	S	S				
Petroleum Products-Unspecified	S					
Polychlorinated biPhenyls (PCB)	S	S				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988