

Cleanup Site ID: 958

Cleanup Site Details

Facility/Site ID: 1671323 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 958

Cleanup Site Name: Midway Metals Glossary

Alternate Names: MIDWAY METALS

LOCATION

Address: 258010 HWY 101 City: PORT ANGELES Zip Code: 98362 County: Clallam

Latitude: 48.08972 Longitude: -123.24083 WRIA: 18 Legislative District: 24 Congressional District: 6 TRS: 30N 4W 18

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Southwest Region Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------------|-----------|------------------|--------------|------------------|--------------------|
| WSDOT property | Upland | Cleanup Started | SW | Southwest Region | Independent Action |
| Midway Metals operation | Upland | Awaiting Cleanup | SW | Southwest Region | Independent Action |

ACTIVE INSTITUTIONAL CONTROLS

| 1 | Instrument Type | Restriction | Restrictions/Requirements | Date | Recording | Recording | Tax Parcel |
|---|-----------------|-------------|-----------------------------|------|-----------|-----------|------------|
| 1 | mstrument Type | Media | ixestrictions/ixequirements | Date | Number | County | Tax Faicei |

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| | MEDIA | | | | | | |
|--------------------------------|-------|-------------|---------------|----------|-----|---------|--|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock | |
| Metals - Other | С | S | S | | | | |
| Metals Priority Pollutants | С | S | S | | S | | |
| Petroleum Products-Unspecified | С | S | S | | S | | |
| Petroleum-Other | С | S | S | | | | |

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|------------------------------|
| Early Notice Letter(s) | Completed | | 3/20/2007 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 3/20/2007 |
| Site Hazard Assessment | Completed | 3/7/2008 | 5/14/2008 |
| Hazardous Sites Listing | Completed | | 5/14/2008 |
| VCP Opinion on Remedial Investigation | Completed | 9/21/2012 | 1/28/2013 |
| VCP Opinion on Property Cleanup | Completed | 9/9/2013 | 10/1/2013 |

Toxics Cleanup Program Report Generated: 11/15/2025 Page 1 of 2



Cleanup Site Details

| SITE ACTIVITIES | | | | | | |
|---------------------------------|-----------|------------|------------------------------|--|--|--|
| Activity | Status | Start Date | End Date/ Completion Date | | | |
| VCP Opinion on Property Cleanup | Completed | 10/30/2013 | 1/27/2014 | | | |
| VCP Status Request | Completed | 5/25/2017 | 6/26/2017 | | | |

Cleanup Site ID: 958