

Cleanup Site Details

Cleanup Site ID: 958

Cleanup Site ID: 958 **Facility/Site ID:** 1671323 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Midway Metals [Glossary](#)
Alternate Names: MIDWAY METALS

LOCATION

Address: 258010 HWY 101 **City:** PORT ANGELES **Zip Code:** 98362 **County:** Clallam
Latitude: 48.08972 **Longitude:** -123.24083 **WRIA:** 18 **Legislative District:** 24 **Congressional District:** 6 **TRS:** 30N 4W 18

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Southwest Region **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------------|-----------|------------------|-----------|------------------|--------------------|
| WSDOT property | Upland | Cleanup Started | SW | Southwest Region | Independent Action |
| Midway Metals operation | Upland | Awaiting Cleanup | SW | Southwest Region | Independent Action |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| Contaminant | MEDIA | | | | | |
|--------------------------------|-------|-------------|---------------|----------|-----|---------|
| | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Metals - Other | C | S | S | | | |
| Metals Priority Pollutants | C | S | S | | S | |
| Petroleum Products-Unspecified | C | S | S | | S | |
| Petroleum-Other | C | S | S | | | |

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|------------------------------|
| Early Notice Letter(s) | Completed | | 3/20/2007 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 3/20/2007 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 3/7/2008 | 5/14/2008 |
| Hazardous Sites Listing/NPL | Completed | | 5/14/2008 |
| VCP Opinion on Remedial Investigation | Completed | 9/21/2012 | 1/28/2013 |
| VCP Opinion on Property Cleanup | Completed | 9/9/2013 | 10/1/2013 |

Cleanup Site Details

Cleanup Site ID: 958

| SITE ACTIVITIES | | | |
|---------------------------------|---------------|-------------------|--------------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| VCP Opinion on Property Cleanup | Completed | 10/30/2013 | 1/27/2014 |
| VCP Status Request | Completed | 5/25/2017 | 6/26/2017 |