

# Cleanup Site Details

Cleanup Site ID: 9596

Cleanup Site ID: 9596      Facility/Site ID: 53522166      UST ID: 7765      [Site Page](#)      [Site Documents](#)      [View Map](#)  
 Cleanup Site Name: ASTRO 106      [Glossary](#)  
 Alternate Names: 106 VISTA 24 HR FUEL, ASTRO 106

## LOCATION

Address: 1401 W 1ST      City: RITZVILLE      Zip Code: 99169      County: Adams  
 Latitude: 47.11705      Longitude: -118.38775      WRIA: 41      Legislative District: 9      Congressional District: 4      TRS: 19N 35E 27

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
 Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? Yes  
 Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
 Site Manager: PLIA      Responsible Unit: Pollution Liability Ins Agcy      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Astro #106	Upland	Cleanup Started	PLIA	PLIA	PLIA Petroleum Technical

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Lead		B				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		9/19/2006
LUST - Site Characterization Report	Completed		8/3/2007
LUST - Report Received	Completed		11/26/2007
LUST - Report Received	Completed		3/5/2008
LUST - Report Received	Completed		8/4/2008
LUST - Report Received	Completed		2/19/2009
LUST - Report Received	Completed		10/23/2009

# Cleanup Site Details

Cleanup Site ID: 9596

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
LUST - Report Received	Completed		9/20/2010
LUST - Report Received	Completed		9/23/2011
VCP Receipt of Plan or Report	Completed		9/25/2015
VCP Receipt of Plan or Report	Completed		2/11/2018