

Cleanup Site Details

Cleanup Site ID: 9617

Cleanup Site ID: 9617 **Facility/Site ID:** 53852761 **UST ID:** 12211 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: WA DOT Anatone Maintenance Site [Glossary](#)
Alternate Names: WA DOT ANATONE MAINTENANCE SITE

LOCATION

Address: SR 129 MP 17.4 WESTSIDE **City:** ANATONE **Zip Code:** 99401 **County:** Asotin
Latitude: 46.13333 **Longitude:** -117.13335 **WRIA:** 35 **Legislative District:** 9 **Congressional District:** 5 **TRS:** 8N 45E 35

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 4/15/2024 **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** Independent Cleanup Reviewed by Ecology **Brownfield?** No
Site Manager: Kercher, Beth **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
DOT MAINTENANCE SITE	Upland	No Further Action Required	EA	Kercher, Beth	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		9/22/1993
LUST - Report Received	Completed		3/4/1994
Site Status Changed to NFA	Completed		4/15/2024