

Cleanup Site Details

Cleanup Site ID: 9646 Facility/Site ID: 54565663 UST ID: 10715 Site Page Site Documents View Map

Cleanup Site ID: 9646

Cleanup Site Name: Camas Port of Washougal

Alternate Names: Camas Port of Washougal, CORROSION SPECIALTIES INC, FABRICON INC, INDUSTRIAL PARK WAREHOUSE, Plains

Marketing Camas

LOCATION

Address: 531 S 28TH ST City: WASHOUGAL Zip Code: 98671 County: Clark

Latitude: 45.57306 Longitude: -122.34184 WRIA: 28 Legislative District: 18 Congressional District: 3 TRS: 1N 4E 47

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Kasperski, Joseph Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
PORT OF CAMAS/WASHOUGAL	Upland	Cleanup Started	SW	Kasperski, Joseph	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene	В						
Other Non-Halogenated Organics	В						
Petroleum-Diesel	S						
Petroleum-Gasoline	С						

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date	
LUST - Notification	Completed		8/20/1989	
Site Discovery/Release Report Received	Completed		8/20/1989	
Initial Investigation / Federal Preliminary Assessment	Completed		12/12/2011	
Early Notice Letter(s)	Completed		4/17/2013	
SHARP Assessment	Completed		8/28/2025	
LUST Review Memo	Completed		8/28/2025	

Toxics Cleanup Program Report Generated: 10/22/2025 Page 1 of 1