

Cleanup Site ID: 9775

Cleanup Site Details

Facility/Site ID: 57487227 UST ID: 419 Site Page Site Documents View Map

Cleanup Site ID: 9775

Cleanup Site Name: Bellingham SD Bus Garage Glossary

Alternate Names: Bellingham SD Bus Garage, BUS GARAGE TRANSPORTATION, BUS GARAGE/TRANSPORTATION

LOCATION

Address: 1801 JAMES ST City: BELLINGHAM Zip Code: 98225 County: Whatcom

Latitude: 48.75408 Longitude: -122.46509 WRIA: 1 Legislative District: 40 Congressional District: 2 TRS: 38N 3E 30

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 6/22/2012 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Initial Investigation Brownfield? Yes

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 BELLINGHAM SCHOOL DIST
 Upland
 No Further Action Required
 NW
 Northwest Region
 Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant Soil Groundwater Surface Water Sediment Air Bedrock
Petroleum-Diesel C

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

End Date/ **Start Date** Activity Status **Completion Date** LUST - Notification Completed 4/13/1990 Site Discovery/Release Report Received Completed 4/13/1990 Completed 5/23/1990 LUST - Report Received 6/2/2011 Initial Investigation / Federal Preliminary Assessment Completed Site Status Changed to NFA Completed 6/22/2012

Toxics Cleanup Program Report Generated: 6/30/2024 Page 1 of 1