

Cleanup Site Details

Cleanup Site ID: 9775 Facility/Site ID: 57487227 UST ID: 419 Site Page Site Documents View Map

Cleanup Site ID: 9775

Cleanup Site Name: Bellingham SD Bus Garage

Alternate Names: Bellingham SD Bus Garage, BUS GARAGE TRANSPORTATION, BUS GARAGE/TRANSPORTATION

LOCATION

Address: 1801 JAMES ST City: BELLINGHAM Zip Code: 98225 County: Whatcom

Latitude: 48.75408 Longitude: -122.46509 WRIA: 1 Legislative District: 40 Congressional District: 2 TRS: 38N 3E 30

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? Yes

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name Unit Type Unit Status Resp Unit Manager Current Process

BELLINGHAM SCHOOL DIST Upland No Further Action Required NW Northwest Region Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/13/1990
Site Discovery/Release Report Received	Completed		4/13/1990
LUST - Report Received	Completed		5/23/1990
Initial Investigation / Federal Preliminary Assessment	Completed		6/2/2011
Site Status Changed to NFA	Completed		6/22/2012
Reopen Site	Completed		3/21/2024

Toxics Cleanup Program Report Generated: 8/26/2025 Page 1 of 1